



Vending Care....

Work Order Details

Job Details

Asset No 00053 **Job Creation Date** 12/19/2016 3:29:15 PM

Job Start Location No Location Found **Job End Location** No Location Found

Job Start Date 12/19/2016 3:41:39 PM **Job Finish Date** 12/19/2016 3:47:35 PM

Customer Contact No 7532939133 **Customer Email**

Present Status Completed

Remarks pm done ok machine working

Ingredient Details

Ingredient	Water	Premix	Temperature	Counter
Hot Lemon Tea	95.00	10.40	76.00	1235.00
Coffee	100.00	11.90	80.00	25480.00
Tea Bag with DW	98.00	11.00	79.00	21781.00
Cardamom Tea	99.00	11.20	81.00	32560.00

Job Images



(http://vendingcare.in/vendingcare/Images/JobImages/72798_1.png)



(http://vendingcare.in/vendingcare/Images/JobImages/72798_2.png)



(http://vendingcare.in/vendingcare/Images/JobImages/72798_3.png)



(http://vendingcare.in/vendingcare/Images/JobImages/72798_4.png)

Work Order Checklist

Parameter Type	Parameter	value
SAFETY		
	Good Condition of 3 pin 15 Amp Plug socket	✓
	Effective Earthing	✓
BRANDING		
	No of gell spots found	✓

Parameter Type	Parameter	value
	Overall body condition	✓
	Brand and keypad stickers in good condition	✓
HYGIENE		
	Cleaning and operational instruction sticker	✓
PART CLEANED		
	Application of cockroach Gel	✗
	Availability of Canister Elbow	✓
	Working of Exhaust Fan	✓
	Stream Exhaust hose pipe	✓
	M/C Body (inner and outer)	✓
	Canisters	✓
	Dispensing valves	✓
	Silicon Tubes	✓
	Boiler Tank and Water Tank	✓
	Dispensing Nozzle	✓
	Drip Try	✓
	Mixing Unit	✓

Signature[BACK TO LIST \(/VENDINGCARE/WORKORDER/INDEX?LENGTH=3\)](#)

copyright 2015