



Vending Care....

Work Order Details

Job Details

Asset No 00102 **Job Creation Date** 12/21/2016 11:03:36 AM

Job Start Location No Location Found **Job End Location** No Location Found

Job Start Date 12/21/2016 11:06:11 AM **Job Finish Date** 12/21/2016 12:00:15 PM

Customer Contact No 9650182188 **Customer Email** sudhirsst56@yahoo.co.in

Present Status Completed

Remarks

Ingredient Details

Ingredient	Water	Premix	Temperature	Counter
Cardamom Tea	133.00	13.46	83.90	170985.00
Coffee	132.00	14.32	82.70	143261.00

Job Images



(http://vendingcare.in/vendingcare/Images/JobImages/73212_1.png)



(http://vendingcare.in/vendingcare/Images/JobImages/73212_2.png)



(http://vendingcare.in/vendingcare/Images/JobImages/73212_3.png)

Work Order Checklist

Parameter Type	Parameter	value
SAFETY		
	Good Condition of 3 pin 15 Amp Plug socket	✓
	Effective Earthing	✗
BRANDING		
	No of gell spots found	✗
	Overall body condition	✓
	Brand and keypad stickers in good condition	✓
HYGIENE		
	Cleaning and operational instruction sticker	✓
PART CLEANED		

Parameter Type	Parameter	value
	Application of cockroach Gel	✘
	Availability of Canister Elbow	✓
	Working of Exhaust Fan	✓
	Stream Exhaust hose pipe	✓
	M/C Body (inner and outer)	✓
	Canisters	✓
	Dispensing valves	✓
	Silicon Tubes	✓
	Boiler Tank and Water Tank	✓
	Dispensing Nozzle	✓
	Drip Try	✓
	Mixing Unit	✓

Signature[BACK TO LIST \(/VENDINGCARE/WORKORDER/INDEX?LENGTH=3\)](#)

copyright 2015