



## Vending Care....

## Work Order Details

## Job Details

**Asset No** 00103 **Job Creation Date** 1/31/2017 6:35:17 PM

**Job Start Location** No Location Found **Job End Location** No Location Found

**Job Start Date** 1/31/2017 6:48:39 PM **Job Finish Date** 1/31/2017 6:52:37 PM

**Customer Contact No** 9810239236 **Customer Email**

**Present Status** Completed

## Remarks


## Ingredient Details

Ingredient	Water	Premix	Temperature	Counter
Cardamom Tea	92.00	12.81	79.00	30956.00
Coffee	92.00	6.31	80.10	73056.00
Hot Lemon Tea	95.00	10.46	78.00	75021.00
Soup	95.00	8.01	81.00	49012.00


## Job Images



([http://vendingcare.in/vendingcare/Images/JobImages/80867\\_1.png](http://vendingcare.in/vendingcare/Images/JobImages/80867_1.png))



([http://vendingcare.in/vendingcare/Images/JobImages/80867\\_2.png](http://vendingcare.in/vendingcare/Images/JobImages/80867_2.png))



([http://vendingcare.in/vendingcare/Images/JobImages/80867\\_3.png](http://vendingcare.in/vendingcare/Images/JobImages/80867_3.png))

## Work Order Checklist

Parameter Type	Parameter	value
SAFETY		
	EffectiveEarthing	✓
	Good Condition of 3 pin 15 Amp Plug socket	✓
BRANDING		
	Brand and keypad stickers in good condition	✓
	Overall body condition	✗
	No of gell spots found	✗
HYGIENE		

Parameter Type	Parameter	value
	Cleaning and operational instruction sticker	✓
<b>PART CLEANED</b>		
	Mixing Unit	✓
	Drip Try	✓
	Dispensing Nozzle	✓
	Boiler Tank and Water Tank	✓
	Silicon Tubes	✓
	Dispensing valves	✓
	Canisters	✓
	M/C Body (inner and outer)	✓
	Stream Exhaust hose pipe	✓
	Working of Exhaust Fan	✓
	Availability of Canister Elbow	✓
	Application of cockroach Gel	✗

**Signature**



[BACK TO LIST \(/VENDINGCARE/WORKORDER/INDEX?LENGTH=3\)](#)

copyright 2015