



# Vending Care....

## Work Order Details

### Job Details

**Asset No** 00377 **Job Creation Date** 2/27/2017 4:46:46 PM

**Job Start Location** No Location Found **Job End Location** No Location Found

**Job Start Date** 2/27/2017 5:00:55 PM **Job Finish Date** 2/27/2017 5:13:30 PM

**Customer Contact No** 8010799541 **Customer Email**

**Present Status** Completed

**Remarks** installation of

### Ingredient Details

Ingredient	Water	Premix	Temperature	Counter
Tea Bag with DW	135.00	10.96	63.00	2.00
Coffee	130.00	13.93	68.00	1.00

### Job Images



([http://vendingcare.in/vendingcare/Images/JobImages/86118\\_1.png](http://vendingcare.in/vendingcare/Images/JobImages/86118_1.png))



([http://vendingcare.in/vendingcare/Images/JobImages/86118\\_2.png](http://vendingcare.in/vendingcare/Images/JobImages/86118_2.png))



([http://vendingcare.in/vendingcare/Images/JobImages/86118\\_3.png](http://vendingcare.in/vendingcare/Images/JobImages/86118_3.png))

### Work Order Checklist

Parameter Type	Parameter	value
<b>SAFETY</b>		
	Effective Earthing	✓
	Good Condition of 3 pin 15 Amp Plug socket	✓
<b>BRANDING</b>		
	Brand and keypad stickers in good condition	✓
	Overall body condition	✗
	No of gell spots found	✗
<b>HYGIENE</b>		
	Cleaning and operational instruction sticker	✗
<b>PART CLEANED</b>		

Parameter Type	Parameter	value
	Mixing Unit	✘
	Drip Try	✘
	Dispensing Nozzle	✘
	Boiler Tank and Water Tank	✘
	Silicon Tubes	✘
	Dispensing valves	✘
	Canisters	✘
	M/C Body (inner and outer)	✘
	Stream Exhaust hose pipe	✘
	Working of Exhaust Fan	✘
	Availability of Canister Elbow	✘
	Application of cockroach Gel	✘

**Signature**



[BACK TO LIST \(/VENDINGCARE/WORKORDER/INDEX?LENGTH=3\)](#)

copyright 2015