



Vending Care....

Work Order Details

Job Details

Asset No 00489 **Job Creation Date** 5/6/2017 4:54:05 PM
Job Start Location **Job End Location** No Location Found
Job Start Date **Job Finish Date** 5/6/2017 5:27:22 PM
Customer Contact No 9711614124 **Customer Email** kanishk.tokas63@gmail.com

Present Status Completed

Remarks TDS-58

Ingredient Details

Ingredient	Water	Premix	Temperature	Counter
Cardamom Tea	75.00	10.20	80.40	3124.00
Hot Lemon Tea	75.00	6.40	80.00	6408.00
Coffee	75.00	10.40	80.50	10003.00

Job Images



(http://vendingcare.in/vendingcare/Images/JobImages/99078_1.png)



(http://vendingcare.in/vendingcare/Images/JobImages/99078_2.png)



(http://vendingcare.in/vendingcare/Images/JobImages/99078_3.png)

Work Order Checklist

Parameter Type	Parameter	value
SAFETY		
	EffectiveEarthing	✓
	Good Condition of 3 pin 15 Amp Plug socket	✓
BRANDING		
	Brand and keypad stickers in good condition	✓
	Overall body condition	✓
	No of gell spots found	✓
HYGIENE		
	Cleaning and operational instruction sticker	✓

Parameter Type	Parameter	value
PART CLEANED		
	Mixing Unit	✓
	Drip Try	✓
	Dispensing Nozzle	✓
	Boiler Tank and Water Tank	✓
	Silicon Tubes	✓
	Dispensing valves	✓
	Canisters	✓
	M/C Body (inner and outer)	✓
	Stream Exhaust hose pipe	✓
	Working of Exhaust Fan	✓
	Availability of Canister Elblow	✓
	Application of cockroach Gel	✗

Signature[BACK TO LIST \(VENDINGCARE/WORKORDER/INDEX?LENGTH=3\)](#)

copyright 2015