



Vending Care....

Work Order Details

Job Details

Asset No 00568 **Job Creation Date** 2/6/2017 12:11:59 PM

Job Start Location No Location Found **Job End Location** No Location Found

Job Start Date 2/6/2017 12:14:39 PM **Job Finish Date** 2/6/2017 12:25:34 PM

Customer Contact No 7503979513 **Customer Email** no

Present Status Completed

Remarks ok TDS=53 9:50 to 12:25

Ingredient Details

Ingredient	Water	Premix	Temperature	Counter
Hot water	110.00	0.00	74.90	5990.00
Coffee	72.00	16.30	74.30	7634.00
Tea Bag with DW	92.00	12.40	74.90	118860.00


Job Images



(http://vendingcare.in/vendingcare/Images/JobImages/81853_1.png)



(http://vendingcare.in/vendingcare/Images/JobImages/81853_2.png)



(http://vendingcare.in/vendingcare/Images/JobImages/81853_3.png)



(http://vendingcare.in/vendingcare/Images/JobImages/81853_4.png)



(http://vendingcare.in/vendingcare/Images/JobImages/81853_5.png)

Work Order Checklist

Parameter Type	Parameter	value
SAFETY		
	EffectiveEarthing	✓
	Good Condition of 3 pin 15 Amp Plug socket	✓
BRANDING		
	Brand and keypad stickers in good condition	✓

Parameter Type	Parameter	value
	Overall body condition	✓
	No of gell spots found	✗
HYGIENE		
	Cleaning and operational instruction sticker	✓
PART CLEANED		
	Mixing Unit	✓
	Drip Try	✓
	Dispensing Nozzle	✓
	Boiler Tank and Water Tank	✗
	Silicon Tubes	✗
	Dispensing valves	✗
	Canisters	✗
	M/C Body (inner and outer)	✗
	Stream Exhaust hose pipe	✗
	Working of Exhaust Fan	✗
	Availability of Canister Elbow	✗
	Application of cockroach Gel	✗

Signature

RK-S

[BACK TO LIST \(/VENDINGCARE/WORKORDER/INDEX?LENGTH=3\)](#)

copyright 2015