

Vending Care....



ak2 ▾

Work Order Details

Job Details

Asset No 00679 **Job Creation Date** 12/26/2016 5:51:09 PM

Job Start Location No Location Found **Job End Location** No Location Found

Job Start Date 12/26/2016 5:59:51 PM **Job Finish Date** 12/26/2016 6:19:39 PM

Customer Contact No 9811212866 **Customer Email**

Present Status Completed

Remarks insttallation 2line ac grup vending machine ok done

Ingredient Details

Ingredient	Water	Premix	Temperature	Counter
Soup	100.00	10.10	80.00	211112.00
Cardamom Tea	105.00	11.60	81.00	75919.00


Job Images



(http://vendingcare.in/vendingcare/Images/JobImages/74233_1.png)



(http://vendingcare.in/vendingcare/Images/JobImages/74233_2.png)



(http://vendingcare.in/vendingcare/Images/JobImages/74233_3.png)

Work Order Checklist

Parameter Type	Patameter	value
SAFETY		
	EffectiveEarthing	✓
	Good Condition of 3 pin 15 Amp Plug socket	✓
BRANDING		
	Brand and keypad stickers in good condition	✓
	Overall body condition	✓
	No of gell spots found	✓
HYGIENE		
	Cleaning and operational instruction sticker	✓
PART CLEANED		

Parameter Type	Parameter	value
	Mixing Unit	✓
	Drip Try	✗
	Dispensing Nozzle	✓
	Boiler Tank and Water Tank	✓
	Silicon Tubes	✓
	Dispensing valves	✓
	Canisters	✗
	M/C Body (inner and outer)	✓
	Stream Exhaust hose pipe	✓
	Working of Exhaust Fan	✓
	Availability of Canister Elbow	✗
	Application of cockroach Gel	✓

Signature[BACK TO LIST \(/VENDINGCARE/WORKORDER/INDEX?LENGTH=3\)](#)

copyright 2015