Vending Care....



Work Order Details

Job Details

Asset No 00694 Job Creation Date 12/9/2016 4:06:02 PM

Job Start Location No Location Found Job End Location No Location Found

Job Start Date 12/9/2016 4:09:00 PM Job Finish Date 12/9/2016 4:18:25 PM

Customer Contact No 8585999710 Customer Email majestic atuo gr noida up

Present Status Completed

Remarks pm done ok(canester elbwo nhi hai)

Ingredient Details

Ingredient	Water	Premix	Temperature	Counter	
Cardamom Tea	80.00	11.34	84.60	14153.00	
Coffee	80.00	11.38	85.00	14960.00	

Job Images



(http://vendingcare.in/vendingcare/Images/JobImages/70877_1.png)



(http://vendingcare.in/vendingcare/Images/JobImages/70877_2.png)



(http://vendingcare.in/vendingcare/Images/JobImages/70877_3.png)

Work Order Checklist

Parameter Type	Patameter	value
SAFETY		
	EffectiveEarthing	✓
	Good Condition of 3 pin 15 Amp Plug socket	✓
BRANDING		
	Brand and keypad stickers in good condition	✓
	Overall body condition	✓
	No of gell spots found	✓
HYGIENE		
	Cleaning and operational instruction sticker	✓
PART CLEANED		

Parameter Type	Patameter	value
	Mixing Unit	✓
	Drip Try	✓
	Dispensing Nozzle	✓
	Boiler Tank and Water Tank	✓
	Silicon Tubes	✓
	Dispensing valves	✓
	Canisters	✓
	M/C Body (inner and outer)	✓
	Stream Exhaust hose pipe	✓
	Working of Exhaust Fan	✓
	Availability of Canister Elblow	×
	Application of cockroach Gel	✓

Signature

ramodi

BACK TO LIST (/VENDINGCARE/WORKORDER/INDEX?LENGTH=3)

copyright 2015