



# Vending Care....

## Work Order Details

### Job Details

**Asset No** 01647 **Job Creation Date** 12/16/2016 11:30:10 AM  
**Job Start Location** **Job End Location** No Location Found  
**Job Start Date** **Job Finish Date** 12/16/2016 12:45:25 PM  
**Customer Contact No** 9717217776 **Customer Email** sandeepgchopra01agmail.com

**Present Status** Completed

**Remarks** OK tray milk bag20

### Ingredient Details

Ingredient	Water	Premix	Temperature	Counter
Latte with Fresh milk	10.00	0.90	82.10	2.00
Cappucinno with Fresh milk	10.00	1.20	80.10	1.00

### Job Images



([http://vendingcare.in/vendingcare/Images/JobImages/72213\\_1.png](http://vendingcare.in/vendingcare/Images/JobImages/72213_1.png))



([http://vendingcare.in/vendingcare/Images/JobImages/72213\\_2.png](http://vendingcare.in/vendingcare/Images/JobImages/72213_2.png))



([http://vendingcare.in/vendingcare/Images/JobImages/72213\\_3.png](http://vendingcare.in/vendingcare/Images/JobImages/72213_3.png))



([http://vendingcare.in/vendingcare/Images/JobImages/72213\\_4.png](http://vendingcare.in/vendingcare/Images/JobImages/72213_4.png))

### Work Order Checklist

Parameter Type	Parameter	value
<b>SAFETY</b>		
	EffectiveEarthing	✓
	Good Condition of 3 pin 15 Amp Plug socket	✓
<b>BRANDING</b>		
	Brand and keypad stickers in good condition	✓
	Overall body condition	✓
	No of gell spots found	✗

Parameter Type	Parameter	value
<b>HYGIENE</b>		
	Cleaning and operational instruction sticker	✘
<b>PART CLEANED</b>		
	Mixing Unit	✘
	Drip Try	✔
	Dispensing Nozzle	✔
	Boiler Tank and Water Tank	✔
	Silicon Tubes	✔
	Dispensing valves	✔
	Canisters	✘
	M/C Body (inner and outer)	✔
	Stream Exhaust hose pipe	✔
	Working of Exhaust Fan	✔
	Availability of Canister Elbow	✘
	Application of cockroach Gel	✔

**Signature**[BACK TO LIST \(/VENDINGCARE/WORKORDER/INDEX?LENGTH=3\)](#)

copyright 2015