# Vending Care....



### **Work Order Details**

Job Details

Asset No 02008 Job Creation Date 1/23/2017 12:37:03 PM

Job Start Location No Location Found Job End Location No Location Found

Job Start Date 1/24/2017 11:43:49 AM Job Finish Date 1/24/2017 12:34:13 PM

Customer Contact No 4275402728 Customer Email goneek.migrani@gmail.com

Present Status Completed

Remarks

#### **Ingredient Details**

Ingredient	Water	Premix	Temperature	Counter
Tea bag with Fresh milk	46.00	43.00	82.00	7043.00
Latte with Fresh milk	68.00	0.80	80.00	8988.00
Cappucinno with Fresh milk	64.00	1.10	78.00	9050.00

#### Job Images



(http://vendingcare.in/vendingcare/Images/JobImages/79254\_1.png)



(http://vendingcare.in/vendingcare/Images/JobImages/79254\_2.png)



(http://vendingcare.in/vendingcare/Images/JobImages/79254\_3.png)



(http://vendingcare.in/vendingcare/Images/JobImages/79254\_4.png



(http://vendingcare.in/vendingcare/Images/JobImages/79254\_5.png)

#### **Work Order Checklist**

Parameter Type	Patameter	value
SAFETY		
	EffectiveEarthing	✓
	Good Condition of 3 pin 15 Amp Plug socket	✓
BRANDING		
	Brand and keypad stickers in good condition	✓

Parameter Type	Patameter	value
	Overall body condition	✓
	No of gell spots found	<b>&amp;</b>
HYGIENE		
	Cleaning and operational instruction sticker	<b>&amp;</b>
PART CLEANED		
	Mixing Unit	<b>&amp;</b>
	Drip Try	✓
	Dispensing Nozzle	✓
	Boiler Tank and Water Tank	8
	Silicon Tubes	8
	Dispensing valves	8
	Canisters	8
	M/C Body (inner and outer)	8
	Stream Exhaust hose pipe	8
	Working of Exhaust Fan	1
	Availability of Canister Elblow	8
	Application of cockroach Gel	8

## Signature

. - }

BACK TO LIST (/VENDINGCARE/WORKORDER/INDEX?LENGTH=3)

copyright 2015