



Vending Care....

Work Order Details

Job Details

Asset No 02030 **Job Creation Date** 2/8/2017 5:07:31 PM

Job Start Location No Location Found **Job End Location** No Location Found

Job Start Date 2/8/2017 5:49:58 PM **Job Finish Date** 2/8/2017 6:32:17 PM

Customer Contact No 8527847474 **Customer Email**

Present Status Completed

Remarks intallation done...


Ingredient Details

Ingredient	Water	Premix	Temperature	Counter
Coffee	98.00	12.89	78.70	39001.00
Tea Bag with DW	96.00	11.67	78.60	114174.00

Job Images



(http://vendingcare.in/vendingcare/Images/JobImages/82399_1.png)



(http://vendingcare.in/vendingcare/Images/JobImages/82399_2.png)



(http://vendingcare.in/vendingcare/Images/JobImages/82399_3.png)



(http://vendingcare.in/vendingcare/Images/JobImages/82399_4.png)

Work Order Checklist

Parameter Type	Patameter	value
SAFETY		
	EffectiveEarthing	✓
	Good Condition of 3 pin 15 Amp Plug socket	✓
BRANDING		
	Brand and keypad stickers in good condition	✓
	Overall body condition	✓
	No of gell spots found	✓

Parameter Type	Parameter	value
HYGIENE		
	Cleaning and operational instruction sticker	✓
PART CLEANED		
	Mixing Unit	✓
	Drip Try	✓
	Dispensing Nozzle	✓
	Boiler Tank and Water Tank	✗
	Silicon Tubes	✓
	Dispensing valves	✓
	Canisters	✓
	M/C Body (inner and outer)	✓
	Stream Exhaust hose pipe	✓
	Working of Exhaust Fan	✓
	Availability of Canister Elblow	✓
	Application of cockroach Gel	✓

Signature



[BACK TO LIST \(/VENDINGCARE/WORKORDER/INDEX?LENGTH=3\)](#)

copyright 2015