



Vending Care....

Work Order Details

Job Details

Asset No 02114 **Job Creation Date** 2/9/2017 11:35:06 AM
Job Start Location No Location Found **Job End Location** No Location Found
Job Start Date 2/9/2017 11:41:09 AM **Job Finish Date** 2/9/2017 12:04:39 PM
Customer Contact No 8130036187 **Customer Email** aarti.vaid@hdfcbank.com
Present Status Completed

Remarks OK

Ingredient Details

Ingredient	Water	Premix	Temperature	Counter
Tea Bag with DW	88.00	9.81	82.50	14100.00
Coffee	87.00	11.73	82.10	6727.00

Job Images



(http://vendingcare.in/vendingcare/Images/JobImages/82564_1.png)



(http://vendingcare.in/vendingcare/Images/JobImages/82564_2.png)



(http://vendingcare.in/vendingcare/Images/JobImages/82564_3.png)



(http://vendingcare.in/vendingcare/Images/JobImages/82564_4.png)



(http://vendingcare.in/vendingcare/Images/JobImages/82564_5.png)



(http://vendingcare.in/vendingcare/Images/JobImages/82564_6.png)

Work Order Checklist

Parameter Type	Parameter	value
SAFETY		
	Good Condition of 3 pin 15 Amp Plug socket	✓
	Effective Earthing	✓

Parameter Type	Parameter	value
BRANDING		
	No of gell spots found	✘
	Overall body condition	✘
	Brand and keypad stickers in good condition	✘
HYGIENE		
	Cleaning and operational instruction sticker	✘
PART CLEANED		
	Application of cockroach Gel	✔
	Availability of Canister Elbow	✔
	Working of Exhaust Fan	✘
	Stream Exhaust hose pipe	✘
	M/C Body (inner and outer)	✘
	Canisters	✔
	Dispensing valves	✘
	Silicon Tubes	✔
	Boiler Tank and Water Tank	✔
	Dispensing Nozzle	✔
	Drip Try	✘
	Mixing Unit	✔

Signature


[BACK TO LIST \(VENDINGCARE/WORKORDER/INDEX?LENGTH=3\)](#)

copyright 2015