



Vending Care....

Work Order Details

Job Details

Asset No 24017 **Job Creation Date** 3/8/2017 2:42:46 PM

Job Start Location A-17, Gurugram, India **Job End Location**

Job Start Date 3/8/2017 2:54:46 PM **Job Finish Date** 3/8/2017 3:12:55 PM

Customer Contact No 8826489204 **Customer Email** mukesh.x.kumar@questdiagnostics.com

Present Status Completed

Remarks tds 28

Ingredient Details

Ingredient	Water	Premix	Temperature	Counter
Cardamom Tea	88.00	13.20	85.00	10.00
Strong Coffee with fresh milk	45.00	5.60	85.00	100.00
Hot Lemon Tea	89.00	10.10	85.00	9.00
Latte with Fresh milk	47.00	0.00	85.00	231.00
Light Coffee with fresh milk	35.00	5.40	85.00	34.00
Americano	67.00	5.70	85.00	49.00

Job Images



(http://vendingcare.in/vendingcare/Images/JobImages/87792_1.png)



(http://vendingcare.in/vendingcare/Images/JobImages/87792_2.png)



(http://vendingcare.in/vendingcare/Images/JobImages/87792_3.png)



(http://vendingcare.in/vendingcare/Images/JobImages/87792_4.png)



(http://vendingcare.in/vendingcare/Images/JobImages/87792_5.png)

Work Order Checklist

Parameter Type	Parameter	value
SAFETY		
	EffectiveEarthing	✓

Parameter Type	Parameter	value
	Good Condition of 3 pin 15 Amp Plug socket	✓
BRANDING		
	Brand and keypad stickers in good condition	✓
	Overall body condition	✓
	No of gell spots found	✓
HYGIENE		
	Cleaning and operational instruction sticker	✓
PART CLEANED		
	Mixing Unit	✓
	Drip Tray	✓
	Dispensing Nozzle	✓
	Boiler Tank and Water Tank	✓
	Silicon Tubes	✓
	Dispensing valves	✓
	Canisters	✓
	M/C Body (inner and outer)	✓
	Stream Exhaust hose pipe	✓
	Working of Exhaust Fan	✓
	Availability of Canister Elbow	✓
	Application of cockroach Gel	✓

Signature


[BACK TO LIST \(/VENDINGCARE/WORKORDER/INDEX?LENGTH=3\)](#)

copyright 2015