



## Vending Care....

## Work Order Details

## Job Details

**Asset No** 26215 **Job Creation Date** 1/31/2017 5:54:52 PM

**Job Start Location** No Location Found **Job End Location** No Location Found

**Job Start Date** 1/31/2017 5:56:33 PM **Job Finish Date** 1/31/2017 6:02:46 PM

**Customer Contact No** 9015061014 **Customer Email** mamittal@indiabulls.com

**Present Status** Completed

## Remarks

## Ingredient Details

Ingredient	Water	Premix	Temperature	Counter
Coffee	91.00	12.44	82.70	44556.00
Tea Bag with DW	90.00	10.00	81.30	50774.00

## Job Images



([http://vendingcare.in/vendingcare/Images/JobImages/80857\\_1.png](http://vendingcare.in/vendingcare/Images/JobImages/80857_1.png))



([http://vendingcare.in/vendingcare/Images/JobImages/80857\\_2.png](http://vendingcare.in/vendingcare/Images/JobImages/80857_2.png))



([http://vendingcare.in/vendingcare/Images/JobImages/80857\\_3.png](http://vendingcare.in/vendingcare/Images/JobImages/80857_3.png))

## Work Order Checklist

Parameter Type	Parameter	value
<b>SAFETY</b>		
	Effective Earthing	✓
	Good Condition of 3 pin 15 Amp Plug socket	✓
<b>BRANDING</b>		
	Brand and keypad stickers in good condition	✓
	Overall body condition	✓
	No of gell spots found	✗
<b>HYGIENE</b>		
	Cleaning and operational instruction sticker	✓
<b>PART CLEANED</b>		

Parameter Type	Parameter	value
	Mixing Unit	✓
	Drip Try	✓
	Dispensing Nozzle	✓
	Boiler Tank and Water Tank	✓
	Silicon Tubes	✓
	Dispensing valves	✓
	Canisters	✓
	M/C Body (inner and outer)	✓
	Stream Exhaust hose pipe	✓
	Working of Exhaust Fan	✗
	Availability of Canister Elbow	✗
	Application of cockroach Gel	✗

**Signature**[BACK TO LIST \(/VENDINGCARE/WORKORDER/INDEX?LENGTH=3\)](#)

copyright 2015