



# Vending Care....

## Work Order Details

### Job Details

**Asset No** 28303 **Job Creation Date** 12/29/2016 1:34:38 PM

**Job Start Location** **Job End Location** No Location Found

**Job Start Date** **Job Finish Date** 12/29/2016 3:08:20 PM

**Customer Contact No** 8239038123 **Customer Email**

**Present Status** Completed

**Remarks** new installation done


### Ingredient Details

Ingredient	Water	Premix	Temperature	Counter
Americano	60.00	0.00	80.00	21.00
Hot water	80.00	0.00	80.00	14.00
Tea bag with Fresh milk	35.00	0.00	80.00	18.00
Latte with Fresh milk	35.00	0.00	80.00	30.00
Cappucinno with Fresh milk	45.00	0.00	80.00	14.00
Cardamom Tea	80.00	11.23	80.00	14.00

### Job Images



([http://vendingcare.in/vendingcare/Images/JobImages/74844\\_1.png](http://vendingcare.in/vendingcare/Images/JobImages/74844_1.png))



([http://vendingcare.in/vendingcare/Images/JobImages/74844\\_2.png](http://vendingcare.in/vendingcare/Images/JobImages/74844_2.png))



([http://vendingcare.in/vendingcare/Images/JobImages/74844\\_3.png](http://vendingcare.in/vendingcare/Images/JobImages/74844_3.png))



([http://vendingcare.in/vendingcare/Images/JobImages/74844\\_4.png](http://vendingcare.in/vendingcare/Images/JobImages/74844_4.png))

### Work Order Checklist

Parameter Type	Parameter	value
SAFETY		
	Effective Earthing	✓
	Good Condition of 3 pin 15 Amp Plug socket	✓

Parameter Type	Parameter	value
<b>BRANDING</b>		
	Brand and keypad stickers in good condition	✓
	Overall body condition	✓
	No of gell spots found	✗
<b>HYGIENE</b>		
	Cleaning and operational instruction sticker	✗
<b>PART CLEANED</b>		
	Mixing Unit	✗
	Drip Try	✗
	Dispensing Nozzle	✗
	Boiler Tank and Water Tank	✗
	Silicon Tubes	✗
	Dispensing valves	✗
	Canisters	✗
	M/C Body (inner and outer)	✗
	Stream Exhaust hose pipe	✗
	Working of Exhaust Fan	✗
	Availability of Canister Elbow	✗
	Application of cockroach Gel	✗

**Signature**


[BACK TO LIST \(VENDINGCARE/WORKORDER/INDEX?LENGTH=3\)](#)

copyright 2015