

Vending Care....



kapil ▾

Work Order Details

Job Details

Asset No 28369 **Job Creation Date** 2/27/2017 1:40:43 PM

Job Start Location **Job End Location** No Location Found

Job Start Date **Job Finish Date** 2/27/2017 2:14:03 PM

Customer Contact No 8003333143 **Customer Email**

Present Status Completed

Remarks new installation done


Ingredient Details

Ingredient	Water	Premix	Temperature	Counter
Americano	70.00	0.00	80.00	16.00
Hot water	80.00	0.00	80.00	8.00
Tea bag with Fresh milk	35.00	0.00	80.00	13.00
Latte with Fresh milk	30.00	0.00	80.00	29.00
Cappucinno with Fresh milk	40.00	0.00	80.00	4.00

Job Images



(http://vendingcare.in/vendingcare/Images/JobImages/86062_1.png)



(http://vendingcare.in/vendingcare/Images/JobImages/86062_2.png)



(http://vendingcare.in/vendingcare/Images/JobImages/86062_3.png)

Work Order Checklist

Parameter Type	Parameter	value
SAFETY		
	Effective Earthing	✓
	Good Condition of 3 pin 15 Amp Plug socket	✓
BRANDING		
	Brand and keypad stickers in good condition	✓
	Overall body condition	✓
	No of gell spots found	✗

Parameter Type	Parameter	value
HYGIENE		
	Cleaning and operational instruction sticker	<input checked="" type="checkbox"/>
PART CLEANED		
	Mixing Unit	<input checked="" type="checkbox"/>
	Drip Tray	<input checked="" type="checkbox"/>
	Dispensing Nozzle	<input checked="" type="checkbox"/>
	Boiler Tank and Water Tank	<input checked="" type="checkbox"/>
	Silicon Tubes	<input checked="" type="checkbox"/>
	Dispensing valves	<input checked="" type="checkbox"/>
	Canisters	<input checked="" type="checkbox"/>
	M/C Body (inner and outer)	<input checked="" type="checkbox"/>
	Stream Exhaust hose pipe	<input checked="" type="checkbox"/>
	Working of Exhaust Fan	<input checked="" type="checkbox"/>
	Availability of Canister Elbow	<input checked="" type="checkbox"/>
	Application of cockroach Gel	<input checked="" type="checkbox"/>

Signature[BACK TO LIST \(/VENDINGCARE/WORKORDER/INDEX?LENGTH=3\)](#)

copyright 2015