



## Vending Care....

## Work Order Details

## Job Details

**Asset No** 28455 **Job Creation Date** 3/29/2017 12:50:42 PM

**Job Start Location** No Location Found **Job End Location** No Location Found

**Job Start Date** 3/29/2017 1:20:30 PM **Job Finish Date** 3/29/2017 1:24:26 PM

**Customer Contact No** 7531912715 **Customer Email**

**Present Status** Completed

**Remarks** ok


## Ingredient Details

Ingredient	Water	Premix	Temperature	Counter
Cardamom Tea	93.00	12.54	83.60	8.00
Hot Lemon Tea	92.00	11.80	82.80	10.00
Coffee	92.00	12.56	84.40	10.00


## Job Images



([http://vendingcare.in/vendingcare/Images/JobImages/90962\\_1.png](http://vendingcare.in/vendingcare/Images/JobImages/90962_1.png))



([http://vendingcare.in/vendingcare/Images/JobImages/90962\\_2.png](http://vendingcare.in/vendingcare/Images/JobImages/90962_2.png))



([http://vendingcare.in/vendingcare/Images/JobImages/90962\\_3.png](http://vendingcare.in/vendingcare/Images/JobImages/90962_3.png))

## Work Order Checklist

Parameter Type	Parameter	value
SAFETY		
	EffectiveEarthing	✓
	Good Condition of 3 pin 15 Amp Plug socket	✓
BRANDING		
	Brand and keypad stickers in good condition	✓
	Overall body condition	✗
	No of gell spots found	✗
HYGIENE		
	Cleaning and operational instruction sticker	✓

Parameter Type	Parameter	value
PART CLEANED		
	Mixing Unit	✓
	Drip Try	✓
	Dispensing Nozzle	✓
	Boiler Tank and Water Tank	✓
	Silicon Tubes	✓
	Dispensing valves	✓
	Canisters	✓
	M/C Body (inner and outer)	✓
	Stream Exhaust hose pipe	✓
	Working of Exhaust Fan	✓
	Availability of Canister Elbow	✓
	Application of cockroach Gel	✓

**Signature**[BACK TO LIST \(/VENDINGCARE/WORKORDER/INDEX?LENGTH=3\)](#)

copyright 2015