

# Vending Care....



## Work Order Details

### Job Details

**Asset No** 28566 **Job Creation Date** 10/18/2019 2:18:08 PM

**Job Start Location** No Location Found **Job End Location** No Location Found

**Job Start Date** 10/18/2019 2:19:14 PM **Job Finish Date** 10/18/2019 4:57:25 PM

**Customer Contact No** +919389990465 **Customer Email**


**Present Status** Completed

### Remarks

### Ingredient Details

Ingredient	Water	Premix	Temperature	Counter
Cappucinno with Fresh milk	35.00	7.00	84.00	13.00
Tea bag with Fresh milk	35.00	55.00	84.00	79.00
Latte with Fresh milk	35.00	7.00	84.00	854.00
Americano	35.00	7.00	84.00	801.00

### Job Images



([http://vendingcare.in/vendingcare/Images/JobImages/379332\\_1.png](http://vendingcare.in/vendingcare/Images/JobImages/379332_1.png))



([http://vendingcare.in/vendingcare/Images/JobImages/379332\\_2.png](http://vendingcare.in/vendingcare/Images/JobImages/379332_2.png))



([http://vendingcare.in/vendingcare/Images/JobImages/379332\\_3.png](http://vendingcare.in/vendingcare/Images/JobImages/379332_3.png))



([http://vendingcare.in/vendingcare/Images/JobImages/379332\\_4.png](http://vendingcare.in/vendingcare/Images/JobImages/379332_4.png))

## Work Order Checklist

Parameter Type	Parameter	value
<b>SAFETY</b>		
	Effective Earthing	✓
	Good Condition of 3 pin 15 Amp Plug socket	✓
<b>BRANDING</b>		
	No of gell spots found	✓
	Brand and keypad stickers in good condition	✓
	Overall body condition	✓
<b>HYGIENE</b>		
	Cleaning and operational instruction sticker	✓
<b>PART CLEANED</b>		
	Mixing Unit	✓
	Drip Tray	✓
	Dispensing Nozzle	✓
	Boiler Tank and Water Tank	✓
	Silicon Tubes	✓

Parameter Type	Parameter	value
	Dispensing valves	✓
	Canisters	✓
	M/C Body (inner and outer)	✓
	Stream Exhaust hose pipe	✓
	Working of Exhaust Fan	✓
	Availability of Canister Elbow	✓
	Application of cockroach Gel	✓

## Signature



[BACK TO LIST \(/VENDINGCARE/WORKORDER/INDEX?LENGTH=3\)](#)

copyright 2015