# Vending Care....



### **Work Order Details**

Job Details

Asset No 30611 Job Creation Date 1/12/2017 5:11:52 PM

Job Start Location Job End Location No Location Found

Job Start Date Job Finish Date 1/12/2017 6:28:07 PM

Customer Contact No 9829258063 Customer Email

Present Status Completed

Remarks new installation done

#### **Ingredient Details**

Ingredient	Water	Premix	Temperature	Counter
Americano	60.00	0.00	0.00	103.00
Hot water	80.00	0.00	0.00	64.00
Hot Lemon Tea	80.00	9.21	0.00	168.00
Tea bag with Fresh milk	35.00	0.00	0.00	294.00
Latte with Fresh milk	30.00	0.00	0.00	474.00
Cappucinno with Fresh milk	40.00	0.00	0.00	161.00

## Job Images



(http://vendingcare.in/vendingcare/Images/JobImages/77570\_1.png)



(http://vendingcare.in/vendingcare/Images/JobImages/77570\_2.png)



(http://vendingcare.in/vendingcare/Images/JobImages/77570\_3.png)



(http://vendingcare.in/vendingcare/Images/JobImages/77570\_4.png)



(http://vendingcare.in/vendingcare/Images/JobImages/77570\_5.png)

### **Work Order Checklist**

Parameter Type	Patameter	value
SAFETY		
	EffectiveEarthing	<b>√</b>



Parameter Type	Patameter	value
	Good Condition of 3 pin 15 Amp Plug socket	1
BRANDING		
	Brand and keypad stickers in good condition	✓
	Overall body condition	✓
	No of gell spots found	Ø
HYGIENE		
	Cleaning and operational instruction sticker	×
PART CLEANED		
	Mixing Unit	×
	Drip Try	×
	Dispensing Nozzle	<b>(2)</b>
	Boiler Tank and Water Tank	<b>(2)</b>
	Silicon Tubes	Ø
	Dispensing valves	Ø
	Canisters	<b>(2)</b>
	M/C Body (inner and outer)	Ø
	Stream Exhaust hose pipe	×
	Working of Exhaust Fan	×
	Availability of Canister Elblow	×
	Application of cockroach Gel	Ø

# Signature



BACK TO LIST (/VENDINGCARE/WORKORDER/INDEX?LENGTH=3)

copyright 2015