Vending Care....



Work Order Details

Job Details

Asset No 30861 Job Creation Date 12/14/2016 3:47:33 PM

Job Start Location Job End Location No Location Found

Job Start Date Job Finish Date 12/14/2016 3:57:12 PM

Customer Contact No 01124362372 Customer Email

Present Status Completed

Remarks milk warmer no.24046 , with 24046, 15 milk bag.

Ingredient Details

Ingredient	Water	Premix	Temperature	Counter
Latte with Fresh milk	8.00	0.00	82.00	8.00
Cappucinno with Fresh milk	12.00	0.00	82.00	6.00
Tea bag with Fresh milk	50.00	0.00	82.00	4.00
Americano	12.00	0.00	82.00	4.00

Job Images



(http://vendingcare.in/vendingcare/Images/JobImages/71861_1.png)



(http://vendingcare.in/vendingcare/Images/JobImages/71861_2.png)



(http://vendingcare.in/vendingcare/Images/JobImages/71861_3.png)



(http://vendingcare.in/vendingcare/Images/JobImages/71861_4.png)



(http://vendingcare.in/vendingcare/Images/JobImages/71861_5.png)

Work Order Checklist

Parameter Type	Patameter	value
SAFETY		
	EffectiveEarthing	✓
	Good Condition of 3 pin 15 Amp Plug socket	√
BRANDING		

Parameter Type	Patameter	value
	Brand and keypad stickers in good condition	1
	Overall body condition	1
	No of gell spots found	1
HYGIENE		
	Cleaning and operational instruction sticker	✓
PART CLEANED		
	Mixing Unit	✓
	Drip Try	1
	Dispensing Nozzle	✓
	Boiler Tank and Water Tank	✓
	Silicon Tubes	✓
	Dispensing valves	✓
	Canisters	1
	M/C Body (inner and outer)	1
	Stream Exhaust hose pipe	✓
	Working of Exhaust Fan	✓
	Availability of Canister Elblow	✓
	Application of cockroach Gel	8

Signature

BACK TO LIST (/VENDINGCARE/WORKORDER/INDEX?LENGTH=3)

copyright 2015