

Vending Care....



kapil ▾

Work Order Details

Job Details

Asset No 30902 **Job Creation Date** 4/10/2017 6:15:46 PM

Job Start Location No Location Found **Job End Location** No Location Found

Job Start Date 4/10/2017 6:16:13 PM **Job Finish Date** 4/10/2017 6:21:13 PM

Customer Contact No 7340788225 **Customer Email**

Present Status Completed

Remarks instalation done.

Ingredient Details

Ingredient	Water	Premix	Temperature	Counter
Light Coffee with fresh milk	8.60	2.00	70.00	20.00
Cappucinno with Fresh milk	8.00	2.50	70.00	966.00

Job Images



(http://vendingcare.in/vendingcare/Images/JobImages/93708_1.png)



(http://vendingcare.in/vendingcare/Images/JobImages/93708_2.png)



(http://vendingcare.in/vendingcare/Images/JobImages/93708_3.png)



(http://vendingcare.in/vendingcare/Images/JobImages/93708_4.png)

Work Order Checklist

Parameter Type	Parameter	value
SAFETY		
	EffectiveEarthing	✓
	Good Condition of 3 pin 15 Amp Plug socket	✓
BRANDING		
	Brand and keypad stickers in good condition	✓
	Overall body condition	✓
	No of gell spots found	✗

Parameter Type	Parameter	value
HYGIENE		
	Cleaning and operational instruction sticker	✓
PART CLEANED		
	Mixing Unit	✗
	Drip Try	✓
	Dispensing Nozzle	✓
	Boiler Tank and Water Tank	✓
	Silicon Tubes	✓
	Dispensing valves	✗
	Canisters	✗
	M/C Body (inner and outer)	✓
	Stream Exhaust hose pipe	✗
	Working of Exhaust Fan	✓
	Availability of Canister Elbow	✗
	Application of cockroach Gel	✗

Signature[BACK TO LIST \(/VENDINGCARE/WORKORDER/INDEX?LENGTH=3\)](#)

copyright 2015