



Vending Care....

Work Order Details

Job Details

Asset No 31017 **Job Creation Date** 12/31/2016 4:26:28 PM

Job Start Location No Location Found **Job End Location** No Location Found

Job Start Date 12/31/2016 4:51:02 PM **Job Finish Date** 12/31/2016 5:33:21 PM

Customer Contact No 9266655106 **Customer Email** no.email

Present Status Completed

Remarks

Ingredient Details

Ingredient	Water	Premix	Temperature	Counter
Cardamom Tea	94.00	12.69	79.20	228.00
Coffee	95.00	12.71	80.50	263.00

Job Images



(http://vendingcare.in/vendingcare/Images/JobImages/75240_1.png)



(http://vendingcare.in/vendingcare/Images/JobImages/75240_2.png)



(http://vendingcare.in/vendingcare/Images/JobImages/75240_3.png)



(http://vendingcare.in/vendingcare/Images/JobImages/75240_4.png)



(http://vendingcare.in/vendingcare/Images/JobImages/75240_5.png)

Work Order Checklist

Parameter Type	Parameter	value
SAFETY		
	EffectiveEarthing	✓
	Good Condition of 3 pin 15 Amp Plug socket	✓
BRANDING		
	Brand and keypad stickers in good condition	✓
	Overall body condition	✓

Parameter Type	Parameter	value
	No of gell spots found	✘
HYGIENE		
	Cleaning and operational instruction sticker	✓
PART CLEANED		
	Mixing Unit	✓
	Drip Try	✓
	Dispensing Nozzle	✓
	Boiler Tank and Water Tank	✓
	Silicon Tubes	✓
	Dispensing valves	✓
	Canisters	✓
	M/C Body (inner and outer)	✓
	Stream Exhaust hose pipe	✓
	Working of Exhaust Fan	✓
	Availability of Canister Elbow	✓
	Application of cockroach Gel	✘

Signature

PUSPENDER

[BACK TO LIST \(VENDINGCARE/WORKORDER/INDEX?LENGTH=3\)](#)

copyright 2015