



# Vending Care....

## Work Order Details

### Job Details

**Asset No** 31133 **Job Creation Date** 12/31/2016 2:24:09 PM

**Job Start Location** **Job End Location** No Location Found

**Job Start Date** **Job Finish Date** 12/31/2016 3:05:42 PM

**Customer Contact No** 9990145188 **Customer Email**

**Present Status** Completed

### Remarks

### Ingredient Details

Ingredient	Water	Premix	Temperature	Counter
Coffee	150.00	15.60	80.00	11.00
Cardamom Tea	155.00	16.10	80.00	11.00

### Job Images




([http://vendingcare.in/vendingcare/Images/JobImages/75217\\_1.png](http://vendingcare.in/vendingcare/Images/JobImages/75217_1.png))



([http://vendingcare.in/vendingcare/Images/JobImages/75217\\_2.png](http://vendingcare.in/vendingcare/Images/JobImages/75217_2.png))



([http://vendingcare.in/vendingcare/Images/JobImages/75217\\_3.png](http://vendingcare.in/vendingcare/Images/JobImages/75217_3.png))



([http://vendingcare.in/vendingcare/Images/JobImages/75217\\_4.png](http://vendingcare.in/vendingcare/Images/JobImages/75217_4.png))



([http://vendingcare.in/vendingcare/Images/JobImages/75217\\_5.png](http://vendingcare.in/vendingcare/Images/JobImages/75217_5.png))

### Work Order Checklist

Parameter Type	Parameter	value
<b>SAFETY</b>		
	EffectiveEarthing	✓
	Good Condition of 3 pin 15 Amp Plug socket	✓
<b>BRANDING</b>		
	Brand and keypad stickers in good condition	✓
	Overall body condition	✓

Parameter Type	Parameter	value
	No of gell spots found	✓
<b>HYGIENE</b>		
	Cleaning and operational instruction sticker	✓
<b>PART CLEANED</b>		
	Mixing Unit	✓
	Drip Try	✓
	Dispensing Nozzle	✓
	Boiler Tank and Water Tank	✓
	Silicon Tubes	✓
	Dispensing valves	✓
	Canisters	✓
	M/C Body (inner and outer)	✓
	Stream Exhaust hose pipe	✓
	Working of Exhaust Fan	✓
	Availability of Canister Elbow	✓
	Application of cockroach Gel	✓

**Signature**[BACK TO LIST \(VENDINGCARE/WORKORDER/INDEX?LENGTH=3\)](#)

copyright 2015