



Vending Care....

Work Order Details

Job Details

Asset No 31134 **Job Creation Date** 12/31/2016 11:47:23 AM

Job Start Location **Job End Location** No Location Found

Job Start Date **Job Finish Date** 12/31/2016 12:11:06 PM

Customer Contact No 9711878175 **Customer Email**

Present Status Completed

Remarks


Ingredient Details

Ingredient	Water	Premix	Temperature	Counter
Coffee	96.00	12.80	80.00	54.00
Cardamom Tea	95.00	13.50	80.00	14.00

Job Images



(http://vendingcare.in/vendingcare/Images/JobImages/75155_1.png)



(http://vendingcare.in/vendingcare/Images/JobImages/75155_2.png)



(http://vendingcare.in/vendingcare/Images/JobImages/75155_3.png)



(http://vendingcare.in/vendingcare/Images/JobImages/75155_4.png)



(http://vendingcare.in/vendingcare/Images/JobImages/75155_5.png)



(http://vendingcare.in/vendingcare/Images/JobImages/75155_6.png)

Work Order Checklist

Parameter Type	Parameter	value
SAFETY		
	EffectiveEarthing	✓
	Good Condition of 3 pin 15 Amp Plug socket	✓

Parameter Type	Parameter	value
BRANDING		
	Brand and keypad stickers in good condition	✓
	Overall body condition	✓
	No of gell spots found	✓
HYGIENE		
	Cleaning and operational instruction sticker	✓
PART CLEANED		
	Mixing Unit	✓
	Drip Try	✓
	Dispensing Nozzle	✓
	Boiler Tank and Water Tank	✓
	Silicon Tubes	✓
	Dispensing valves	✓
	Canisters	✓
	M/C Body (inner and outer)	✓
	Stream Exhaust hose pipe	✓
	Working of Exhaust Fan	✓
	Availability of Canister Elbow	✓
	Application of cockroach Gel	✓

Signature[BACK TO LIST \(VENDINGCARE/WORKORDER/INDEX?LENGTH=3\)](#)

copyright 2015