



Vending Care....

Work Order Details

Job Details

Asset No 31143 **Job Creation Date** 1/9/2017 5:06:42 PM
Job Start Location No Location Found **Job End Location** No Location Found
Job Start Date 1/9/2017 5:24:16 PM **Job Finish Date** 1/9/2017 5:53:59 PM
Customer Contact No 9711576412 **Customer Email**
Present Status Completed

Remarks instalation done

Ingredient Details

| Ingredient | Water | Premix | Temperature | Counter |
|--------------|-------|--------|-------------|---------|
| Cardamom Tea | 95.00 | 12.50 | 86.00 | 11.00 |
| Coffee | 95.00 | 12.50 | 86.50 | 11.00 |

Job Images



(http://vendingcare.in/vendingcare/Images/JobImages/76920_1.png)



(http://vendingcare.in/vendingcare/Images/JobImages/76920_2.png)



(http://vendingcare.in/vendingcare/Images/JobImages/76920_3.png)



(http://vendingcare.in/vendingcare/Images/JobImages/76920_4.png)



(http://vendingcare.in/vendingcare/Images/JobImages/76920_5.png)

Work Order Checklist

| Parameter Type | Patameter | value |
|-----------------|--|-------|
| SAFETY | | |
| | Good Condition of 3 pin 15 Amp Plug socket | ✓ |
| | EffectiveEarthing | ✓ |
| BRANDING | | |
| | No of gell spots found | ✓ |
| | Overall body condition | ✓ |

| Parameter Type | Parameter | value |
|---------------------|--|-------|
| | Brand and keypad stickers in good condition | ✓ |
| HYGIENE | | |
| | Cleaning and operational instruction sticker | ✓ |
| PART CLEANED | | |
| | Application of cockroach Gel | ✗ |
| | Availability of Canister Elbow | ✓ |
| | Working of Exhaust Fan | ✓ |
| | Stream Exhaust hose pipe | ✓ |
| | M/C Body (inner and outer) | ✓ |
| | Canisters | ✓ |
| | Dispensing valves | ✓ |
| | Silicon Tubes | ✓ |
| | Boiler Tank and Water Tank | ✓ |
| | Dispensing Nozzle | ✓ |
| | Drip Try | ✓ |
| | Mixing Unit | ✓ |

Signature[BACK TO LIST \(VENDINGCARE/WORKORDER/INDEX?LENGTH=3\)](#)

copyright 2015