



Vending Care....

Work Order Details

Job Details

Asset No 31187 **Job Creation Date** 3/2/2017 4:21:17 PM

Job Start Location **Job End Location** No Location Found

Job Start Date **Job Finish Date** 3/2/2017 7:00:44 PM

Customer Contact No 48799700 **Customer Email**

Present Status Completed

Remarks water tds 22

Ingredient Details

Ingredient	Water	Premix	Temperature	Counter
Hot Lemon Tea	100.00	6.98	78.50	16.00
Cardamom Tea	113.00	12.65	78.50	15.00
Tea Bag with DW	105.00	10.45	78.60	14.00
Cappucinno with DW	110.00	10.44	78.40	17.00

Job Images



(http://vendingcare.in/vendingcare/Images/JobImages/86774_1.png)




(http://vendingcare.in/vendingcare/Images/JobImages/86774_2.png)



(http://vendingcare.in/vendingcare/Images/JobImages/86774_3.png)




(http://vendingcare.in/vendingcare/Images/JobImages/86774_4.png)



(http://vendingcare.in/vendingcare/Images/JobImages/86774_5.png)



(http://vendingcare.in/vendingcare/Images/JobImages/86774_6.png)



(http://vendingcare.in/vendingcare/Images/JobImages/86774_7.png)

Work Order Checklist

Parameter Type	Parameter	value
SAFETY		
	Effective Earthing	✓
	Good Condition of 3 pin 15 Amp Plug socket	✓
BRANDING		
	Brand and keypad stickers in good condition	✓
	Overall body condition	✓
	No of gell spots found	✓
HYGIENE		
	Cleaning and operational instruction sticker	✓
PART CLEANED		
	Mixing Unit	✓
	Drip Tray	✓
	Dispensing Nozzle	✓
	Boiler Tank and Water Tank	✗
	Silicon Tubes	✓
	Dispensing valves	✓
	Canisters	✓
	M/C Body (inner and outer)	✓
	Stream Exhaust hose pipe	✓
	Working of Exhaust Fan	✓
	Availability of Canister Elbow	✓
	Application of cockroach Gel	✓

Signature

By Jensen

[BACK TO LIST \(/VENDINGCARE/WORKORDER/INDEX?LENGTH=3\)](#)

copyright 2015