



Vending Care....

Work Order Details

Job Details

Asset No 32976 **Job Creation Date** 3/16/2017 5:51:30 PM
Job Start Location No Location Found **Job End Location** No Location Found
Job Start Date 3/16/2017 5:55:11 PM **Job Finish Date** 3/16/2017 6:05:56 PM
Customer Contact No 8800874901 **Customer Email**
Present Status Completed

Remarks water tds-67

Ingredient Details

Ingredient	Water	Premix	Temperature	Counter
Coffee	102.00	13.56	79.30	1028.00
Cardamom Tea	105.00	13.50	78.10	524.00

Job Images



(http://vendingcare.in/vendingcare/Images/JobImages/88857_1.png)



(http://vendingcare.in/vendingcare/Images/JobImages/88857_2.png)



(http://vendingcare.in/vendingcare/Images/JobImages/88857_3.png)

Work Order Checklist

Parameter Type	Parameter	value
SAFETY		
	Effective Earthing	✓
	Good Condition of 3 pin 15 Amp Plug socket	✓
BRANDING		
	Brand and keypad stickers in good condition	✗
	Overall body condition	✗
	No of gell spots found	✗
HYGIENE		
	Cleaning and operational instruction sticker	✗
PART CLEANED		

Parameter Type	Parameter	value
	Mixing Unit	✘
	Drip Try	✘
	Dispensing Nozzle	✘
	Boiler Tank and Water Tank	✘
	Silicon Tubes	✘
	Dispensing valves	✘
	Canisters	✘
	M/C Body (inner and outer)	✘
	Stream Exhaust hose pipe	✘
	Working of Exhaust Fan	✘
	Availability of Canister Elbow	✘
	Application of cockroach Gel	✘

Signature



[BACK TO LIST \(/VENDINGCARE/WORKORDER/INDEX?LENGTH=3\)](#)

copyright 2015