

# Vending Care....



## Work Order Details

### Job Details

**Asset No** 33997 **Job Creation Date** 11/1/2019 3:51:22 PM

**Job Start Location** **Job End Location**

**Job Start Date** 10/31/2019 5:30:00 PM **Job Finish Date** 10/31/2019 6:30:00 PM

**Customer Contact No** 7928855999 **Customer Email**

**Present Status** Completed

### Remarks


### Spares Used

Spare Part Name	Quantity
Silicon tube 6 X 12	1

### Ingredient Details

Ingredient	Water	Premix	Temperature	Counter
Strong Coffee with DW	70.00	7.00	80.00	16.00
Latte with DW	70.00	7.00	80.00	20.00
Tea Bag with DW	90.00	9.10	80.00	22.00

### Job Images



([http://vendingcare.in/vendingcare/Images/JobImages/384218\\_33997.jpg](http://vendingcare.in/vendingcare/Images/JobImages/384218_33997.jpg))

## Work Order Checklist

Parameter Type	Parameter	value
<b>SAFETY</b>		
	EffectiveEarthing	✓
	Good Condition of 3 pin 15 Amp Plug socket	✓
<b>BRANDING</b>		
	No of gell spots found	✓
	Brand and keypad stickers in good condition	✓
	Overall body condition	✓
<b>HYGIENE</b>		
	Cleaning and operational instruction sticker	✓
<b>PART CLEANED</b>		
	Mixing Unit	✓
	Drip Try	✓
	Dispensing Nozzle	✓
	Boiler Tank and Water Tank	✓
	Silicon Tubes	✓
	Dispensing valves	✓
	Canisters	✓
	M/C Body (inner and outer)	✓
	Stream Exhaust hose pipe	✓
	Working of Exhaust Fan	✓
	Availability of Canister Elblow	✓
	Application of cockroach Gel	✓

## Signature

[BACK TO LIST \(/VENDINGCARE/WORKORDER/INDEX?LENGTH=3\)](#)

copyright 2015