



Vending Care....

Work Order Details

Job Details

Asset No 33998 **Job Creation Date** 3/2/2017 4:14:56 PM

Job Start Location No Location Found **Job End Location** No Location Found

Job Start Date 3/2/2017 4:16:21 PM **Job Finish Date** 3/2/2017 4:44:22 PM

Customer Contact No 1206152157 **Customer Email**

Present Status Completed

Remarks

Ingredient Details

Ingredient	Water	Premix	Temperature	Counter
Tea bag with Fresh milk	45.00	0.00	80.90	1955.00
Latte with Fresh milk	30.00	6.00	80.10	322.00
Cappucinno with Fresh milk	35.00	6.80	80.20	1087.00

Job Images



(http://vendingcare.in/vendingcare/Images/JobImages/86772_1.png)



(http://vendingcare.in/vendingcare/Images/JobImages/86772_2.png)



(http://vendingcare.in/vendingcare/Images/JobImages/86772_3.png)

Work Order Checklist

Parameter Type	Parameter	value
SAFETY		
	EffectiveEarthing	✓
	Good Condition of 3 pin 15 Amp Plug socket	✓
BRANDING		
	Brand and keypad stickers in good condition	✓
	Overall body condition	✓
	No of gell spots found	✗
HYGIENE		
	Cleaning and operational instruction sticker	✗

Parameter Type	Parameter	value
PART CLEANED		
	Mixing Unit	✓
	Drip Try	✓
	Dispensing Nozzle	✓
	Boiler Tank and Water Tank	✓
	Silicon Tubes	✗
	Dispensing valves	✓
	Canisters	✓
	M/C Body (inner and outer)	✗
	Stream Exhaust hose pipe	✗
	Working of Exhaust Fan	✗
	Availability of Canister Elblow	✗
	Application of cockroach Gel	✗

Signature[BACK TO LIST \(VENDINGCARE/WORKORDER/INDEX?LENGTH=3\)](#)

copyright 2015