



# Vending Care....

## Work Order Details

### Job Details

**Asset No** 01266 **Job Creation Date** 3/24/2017 3:45:36 PM  
**Job Start Location** No Location Found **Job End Location** No Location Found  
**Job Start Date** 3/24/2017 3:47:29 PM **Job Finish Date** 3/24/2017 4:43:24 PM  
**Customer Contact No** 9211234598 **Customer Email**  
**Present Status** Completed

### Remarks

### Ingredient Details

Ingredient	Water	Premix	Temperature	Counter
Cardamom Tea	85.00	9.50	75.60	44491.00
Hot Lemon Tea	80.00	8.20	73.80	62261.00
Coffee	84.00	9.90	74.70	47638.00
Soup	85.00	5.00	70.50	12979.00

### Job Images



(http://vendingcare.in/vendingcare/Images/JobImages/90261\_1.png)



(http://vendingcare.in/vendingcare/Images/JobImages/90261\_2.png)



(http://vendingcare.in/vendingcare/Images/JobImages/90261\_3.png)



(http://vendingcare.in/vendingcare/Images/JobImages/90261\_4.png)

### Work Order Checklist

Parameter Type	Parameter	value
<b>SAFETY</b>		
	Effective Earthing	✓
	Good Condition of 3 pin 15 Amp Plug socket	✓
<b>BRANDING</b>		
	Brand and keypad stickers in good condition	✓

Parameter Type	Parameter	value
	Overall body condition	✘
	No of gell spots found	✘
<b>HYGIENE</b>		
	Cleaning and operational instruction sticker	✓
<b>PART CLEANED</b>		
	Mixing Unit	✓
	Drip Try	✓
	Dispensing Nozzle	✓
	Boiler Tank and Water Tank	✓
	Silicon Tubes	✓
	Dispensing valves	✓
	Canisters	✓
	M/C Body (inner and outer)	✓
	Stream Exhaust hose pipe	✓
	Working of Exhaust Fan	✓
	Availability of Canister Elbow	✓
	Application of cockroach Gel	✘

**Signature**[BACK TO LIST \(/VENDINGCARE/WORKORDER/INDEX?LENGTH=3\)](#)

copyright 2015