



Vending Care....

Work Order Details

Job Details

Asset No 02158 **Job Creation Date** 2/1/2017 2:01:36 PM

Job Start Location No Location Found **Job End Location** No Location Found

Job Start Date 2/1/2017 2:07:00 PM **Job Finish Date** 2/1/2017 2:55:20 PM

Customer Contact No 49735600 **Customer Email**

Present Status Completed

Remarks

Ingredient Details

| Ingredient | Water | Premix | Temperature | Counter |
|-----------------|--------|--------|-------------|-----------|
| Coffee | 140.00 | 15.20 | 80.30 | 43542.00 |
| Hot Lemon Tea | 140.00 | 12.20 | 80.60 | 75617.00 |
| Tea Bag with DW | 139.00 | 15.00 | 81.30 | 137068.00 |

Job Images



(http://vendingcare.in/vendingcare/Images/JobImages/81004_1.png)



(http://vendingcare.in/vendingcare/Images/JobImages/81004_2.png)



(http://vendingcare.in/vendingcare/Images/JobImages/81004_3.png)



(http://vendingcare.in/vendingcare/Images/JobImages/81004_4.png)



(http://vendingcare.in/vendingcare/Images/JobImages/81004_5.png)

Work Order Checklist

| Parameter Type | Parameter | value |
|----------------|---|-------|
| SAFETY | | |
| | Effective Earthing | ✓ |
| | Good Condition of 3 pin 15 Amp Plug socket | ✓ |
| BRANDING | | |
| | Brand and keypad stickers in good condition | ✓ |

| Parameter Type | Parameter | value |
|---------------------|--|-------|
| | Overall body condition | ✘ |
| | No of gell spots found | ✘ |
| HYGIENE | | |
| | Cleaning and operational instruction sticker | ✓ |
| PART CLEANED | | |
| | Mixing Unit | ✓ |
| | Drip Try | ✓ |
| | Dispensing Nozzle | ✓ |
| | Boiler Tank and Water Tank | ✓ |
| | Silicon Tubes | ✓ |
| | Dispensing valves | ✓ |
| | Canisters | ✓ |
| | M/C Body (inner and outer) | ✓ |
| | Stream Exhaust hose pipe | ✓ |
| | Working of Exhaust Fan | ✓ |
| | Availability of Canister Elbow | ✓ |
| | Application of cockroach Gel | ✘ |

Signature[BACK TO LIST \(/VENDINGCARE/WORKORDER/INDEX?LENGTH=3\)](#)

copyright 2015