

Vending Care....



ak2 ▾

Work Order Details

Job Details

Asset No 01550 **Job Creation Date** 1/3/2017 2:19:44 PM

Job Start Location No Location Found **Job End Location** No Location Found

Job Start Date 1/3/2017 2:23:19 PM **Job Finish Date** 1/3/2017 2:46:18 PM

Customer Contact No 8860627888 **Customer Email**

Present Status Completed

Remarks OK


Ingredient Details

Ingredient	Water	Premix	Temperature	Counter
Cardamom Tea	95.00	12.65	82.10	139781.00
Coffee	93.00	12.87	82.50	172697.00

Job Images




(http://vendingcare.in/vendingcare/Images/JobImages/75727_1.png)



(http://vendingcare.in/vendingcare/Images/JobImages/75727_2.png)



(http://vendingcare.in/vendingcare/Images/JobImages/75727_3.png)



(http://vendingcare.in/vendingcare/Images/JobImages/75727_4.png)

Work Order Checklist

Parameter Type	Parameter	value
SAFETY		
	Good Condition of 3 pin 15 Amp Plug socket	✓
	Effective Earthing	✓
BRANDING		
	No of gell spots found	✗
	Overall body condition	✓
	Brand and keypad stickers in good condition	✓

Parameter Type	Parameter	value
HYGIENE		
	Cleaning and operational instruction sticker	✘
PART CLEANED		
	Application of cockroach Gel	✔
	Availability of Canister Elbow	✔
	Working of Exhaust Fan	✔
	Stream Exhaust hose pipe	✔
	M/C Body (inner and outer)	✘
	Canisters	✔
	Dispensing valves	✔
	Silicon Tubes	✔
	Boiler Tank and Water Tank	✔
	Dispensing Nozzle	✔
	Drip Try	✔
	Mixing Unit	✔

Signature[BACK TO LIST \(/VENDINGCARE/WORKORDER/INDEX?LENGTH=3\)](#)

copyright 2015