



# Vending Care....

## Work Order Details

### Job Details

**Asset No** 24064 **Job Creation Date** 4/25/2017 5:49:18 PM  
**Job Start Location** No Location Found **Job End Location** No Location Found  
**Job Start Date** 4/25/2017 8:49:05 PM **Job Finish Date** 4/25/2017 8:54:44 PM  
**Customer Contact No** 8950007727 **Customer Email**  
**Present Status** Completed

**Remarks** 24064 bc b2c m/c installatione done

### Ingredient Details

Ingredient	Water	Premix	Temperature	Counter
Plain Tea	100.00	10.50	82.00	728.00
Americano	70.00	7.00	84.00	108.00
Coffee	95.00	12.40	83.00	73.00
Tea bag with Fresh milk	45.00	45.00	84.00	1026.00
Latte with Fresh milk	40.00	7.00	84.00	1289.00
Cappucinno with Fresh milk	40.00	7.00	84.00	72.00

### Job Images



([http://vendingcare.in/vendingcare/Images/JobImages/96702\\_1.png](http://vendingcare.in/vendingcare/Images/JobImages/96702_1.png))



([http://vendingcare.in/vendingcare/Images/JobImages/96702\\_2.png](http://vendingcare.in/vendingcare/Images/JobImages/96702_2.png))




([http://vendingcare.in/vendingcare/Images/JobImages/96702\\_3.png](http://vendingcare.in/vendingcare/Images/JobImages/96702_3.png))

### Work Order Checklist

Parameter Type	Parameter	value
<b>SAFETY</b>		
	Effective Earthing	✓
	Good Condition of 3 pin 15 Amp Plug socket	✓
<b>BRANDING</b>		
	Brand and keypad stickers in good condition	✓
	Overall body condition	✗

Parameter Type	Parameter	value
	No of gell spots found	✘
<b>HYGIENE</b>		
	Cleaning and operational instruction sticker	✔
<b>PART CLEANED</b>		
	Mixing Unit	✘
	Drip Try	✘
	Dispensing Nozzle	✘
	Boiler Tank and Water Tank	✘
	Silicon Tubes	✘
	Dispensing valves	✘
	Canisters	✘
	M/C Body (inner and outer)	✘
	Stream Exhaust hose pipe	✘
	Working of Exhaust Fan	✘
	Availability of Canister Elbow	✘
	Application of cockroach Gel	✘

**Signature**[BACK TO LIST \(VENDINGCARE/WORKORDER/INDEX?LENGTH=3\)](#)

copyright 2015