



## Vending Care....

## Work Order Details

## Job Details

**Asset No** 31192 **Job Creation Date** 4/1/2017 2:33:42 PM

**Job Start Location** **Job End Location** No Location Found

**Job Start Date** **Job Finish Date** 4/1/2017 3:24:15 PM

**Customer Contact No** 8744957091 **Customer Email** No Email id

**Present Status** Completed

**Remarks** TDS-52

## Ingredient Details

Ingredient	Water	Premix	Temperature	Counter
Cardamom Tea	80.00	12.20	80.20	797.00
Hot Lemon Tea	78.00	9.40	78.80	321.00
Tea Bag with DW	80.00	10.40	80.00	2296.00
Coffee	80.00	12.40	80.70	21280.00

## Job Images



([http://vendingcare.in/vendingcare/Images/JobImages/91840\\_1.png](http://vendingcare.in/vendingcare/Images/JobImages/91840_1.png))



([http://vendingcare.in/vendingcare/Images/JobImages/91840\\_2.png](http://vendingcare.in/vendingcare/Images/JobImages/91840_2.png))



([http://vendingcare.in/vendingcare/Images/JobImages/91840\\_3.png](http://vendingcare.in/vendingcare/Images/JobImages/91840_3.png))



([http://vendingcare.in/vendingcare/Images/JobImages/91840\\_4.png](http://vendingcare.in/vendingcare/Images/JobImages/91840_4.png))

## Work Order Checklist

Parameter Type	Parameter	value
SAFETY		
	Effective Earthing	✓
	Good Condition of 3 pin 15 Amp Plug socket	✓
BRANDING		
	Brand and keypad stickers in good condition	✓

Parameter Type	Parameter	value
	Overall body condition	✓
	No of gell spots found	✓
<b>HYGIENE</b>		
	Cleaning and operational instruction sticker	✓
<b>PART CLEANED</b>		
	Mixing Unit	✓
	Drip Try	✓
	Dispensing Nozzle	✓
	Boiler Tank and Water Tank	✓
	Silicon Tubes	✓
	Dispensing valves	✓
	Canisters	✓
	M/C Body (inner and outer)	✓
	Stream Exhaust hose pipe	✓
	Working of Exhaust Fan	✓
	Availability of Canister Elbow	✓
	Application of cockroach Gel	✗

**Signature**

VIKAS

[BACK TO LIST \(/VENDINGCARE/WORKORDER/INDEX?LENGTH=3\)](#)

copyright 2015