



Vending Care....

Work Order Details

Job Details

Asset No 31172 **Job Creation Date** 3/27/2017 5:48:44 PM
Job Start Location No Location Found **Job End Location** No Location Found
Job Start Date 3/27/2017 5:49:48 PM **Job Finish Date** 3/27/2017 5:55:44 PM
Customer Contact No 9910324628 **Customer Email**
Present Status Completed
Remarks 4 lane DC 31172

Ingredient Details

Ingredient	Water	Premix	Temperature	Counter
Cardamom Tea	87.00	12.70	84.00	147.00
Hot Lemon Tea	90.00	12.30	80.00	328.00
Coffee	90.00	12.40	85.00	814.00
Plain Tea	90.00	12.90	82.00	673.00

Job Images



(http://vendingcare.in/vendingcare/Images/JobImages/90655_1.png)



(http://vendingcare.in/vendingcare/Images/JobImages/90655_2.png)



(http://vendingcare.in/vendingcare/Images/JobImages/90655_3.png)

Work Order Checklist

Parameter Type	Parameter	value
SAFETY		
	Effective Earthing	✓
	Good Condition of 3 pin 15 Amp Plug socket	✓
BRANDING		
	Brand and keypad stickers in good condition	✓
	Overall body condition	✓
	No of gell spots found	✗
HYGIENE		

Parameter Type	Parameter	value
	Cleaning and operational instruction sticker	✓
PART CLEANED		
	Mixing Unit	✓
	Drip Try	✓
	Dispensing Nozzle	✓
	Boiler Tank and Water Tank	✓
	Silicon Tubes	✓
	Dispensing valves	✓
	Canisters	✓
	M/C Body (inner and outer)	✓
	Stream Exhaust hose pipe	✓
	Working of Exhaust Fan	✓
	Availability of Canister Elbow	✗
	Application of cockroach Gel	✗

Signature

Ram
CAMS

[BACK TO LIST \(/VENDINGCARE/WORKORDER/INDEX?LENGTH=3\)](#)

copyright 2015