



# Vending Care....

## Work Order Details

### Job Details

**Asset No** 01165 **Job Creation Date** 5/6/2017 5:08:53 PM  
**Job Start Location** No Location Found **Job End Location** No Location Found  
**Job Start Date** 5/6/2017 5:10:06 PM **Job Finish Date** 5/6/2017 5:13:31 PM  
**Customer Contact No** 8218399683 **Customer Email**  
**Present Status** Completed

### Remarks


### Ingredient Details

Ingredient	Water	Premix	Temperature	Counter
Tea Bag with DW	90.00	11.00	77.00	21342.00
Diet Coffee	90.00	7.00	77.40	3216.00


### Job Images



([http://vendingcare.in/vendingcare/Images/JobImages/99085\\_1.png](http://vendingcare.in/vendingcare/Images/JobImages/99085_1.png))



([http://vendingcare.in/vendingcare/Images/JobImages/99085\\_2.png](http://vendingcare.in/vendingcare/Images/JobImages/99085_2.png))



([http://vendingcare.in/vendingcare/Images/JobImages/99085\\_3.png](http://vendingcare.in/vendingcare/Images/JobImages/99085_3.png))

### Work Order Checklist

Parameter Type	Parameter	value
<b>SAFETY</b>		
	Effective Earthing	✓
	Good Condition of 3 pin 15 Amp Plug socket	✓
<b>BRANDING</b>		
	Brand and keypad stickers in good condition	✓
	Overall body condition	✓
	No of gell spots found	✓
<b>HYGIENE</b>		
	Cleaning and operational instruction sticker	✓
<b>PART CLEANED</b>		

Parameter Type	Parameter	value
	Mixing Unit	✓
	Drip Try	✓
	Dispensing Nozzle	✓
	Boiler Tank and Water Tank	✓
	Silicon Tubes	✓
	Dispensing valves	✓
	Canisters	✓
	M/C Body (inner and outer)	✓
	Stream Exhaust hose pipe	✓
	Working of Exhaust Fan	✓
	Availability of Canister Elbow	✓
	Application of cockroach Gel	✗

**Signature**[BACK TO LIST \(/VENDINGCARE/WORKORDER/INDEX?LENGTH=3\)](#)

copyright 2015