



## Vending Care....

## Work Order Details

## Job Details

**Asset No** 02076 **Job Creation Date** 12/19/2016 4:04:51 PM

**Job Start Location** **Job End Location** No Location Found

**Job Start Date** **Job Finish Date** 12/19/2016 5:14:58 PM

**Customer Contact No** 9873080161 **Customer Email** No Email Id

**Present Status** Completed

**Remarks** Mchine insaltion done

## Ingredient Details

Ingredient	Water	Premix	Temperature	Counter
Cardamom Tea	95.00	12.48	82.40	2071.00
Tea Bag with DW	95.00	10.20	81.80	7.00
Coffee	95.00	12.52	82.40	2229.00

## Job Images



([http://vendingcare.in/vendingcare/Images/JobImages/72811\\_1.png](http://vendingcare.in/vendingcare/Images/JobImages/72811_1.png))



([http://vendingcare.in/vendingcare/Images/JobImages/72811\\_2.png](http://vendingcare.in/vendingcare/Images/JobImages/72811_2.png))



([http://vendingcare.in/vendingcare/Images/JobImages/72811\\_3.png](http://vendingcare.in/vendingcare/Images/JobImages/72811_3.png))

## Work Order Checklist

Parameter Type	Patameter	value
SAFETY		
	EffectiveEarthing	✓
	Good Condition of 3 pin 15 Amp Plug socket	✓
BRANDING		
	Brand and keypad stickers in good condition	✓
	Overall body condition	✓
	No of gell spots found	✓
HYGIENE		
	Cleaning and operational instruction sticker	✓

Parameter Type	Parameter	value
PART CLEANED		
	Mixing Unit	✓
	Drip Try	✓
	Dispensing Nozzle	✓
	Boiler Tank and Water Tank	✓
	Silicon Tubes	✓
	Dispensing valves	✓
	Canisters	✓
	M/C Body (inner and outer)	✓
	Stream Exhaust hose pipe	✓
	Working of Exhaust Fan	✓
	Availability of Canister Elbow	✓
	Application of cockroach Gel	✗

**Signature**

SANJAY

[BACK TO LIST \(VENDINGCARE/WORKORDER/INDEX?LENGTH=3\)](#)

copyright 2015