



Vending Care....

Work Order Details

Job Details

Asset No 26708 **Job Creation Date** 5/5/2017 5:24:20 PM
Job Start Location No Location Found **Job End Location** No Location Found
Job Start Date 5/5/2017 5:26:45 PM **Job Finish Date** 5/5/2017 5:35:30 PM
Customer Contact No 9718901161 **Customer Email** shesh.narayan@clearmedi.com
Present Status Completed

Remarks

Ingredient Details

Ingredient	Water	Premix	Temperature	Counter
Tea Bag with DW	78.00	8.32	77.10	16.00
Latte with DW	80.00	6.45	77.40	7.00
Americano	70.00	7.25	77.80	4.00
Cappucino with DW	80.00	7.00	77.30	12.00

Job Images



(http://vendingcare.in/vendingcare/Images/JobImages/98840_1.png)




(http://vendingcare.in/vendingcare/Images/JobImages/98840_2.png)



(http://vendingcare.in/vendingcare/Images/JobImages/98840_3.png)



(http://vendingcare.in/vendingcare/Images/JobImages/98840_4.png)



(http://vendingcare.in/vendingcare/Images/JobImages/98840_5.png)

Work Order Checklist

Parameter Type	Parameter	value
SAFETY		
	Effective Earthing	✓
	Good Condition of 3 pin 15 Amp Plug socket	✓
BRANDING		

Parameter Type	Parameter	value
	Brand and keypad stickers in good condition	✓
	Overall body condition	✓
	No of gell spots found	✓
HYGIENE		
	Cleaning and operational instruction sticker	✓
PART CLEANED		
	Mixing Unit	✓
	Drip Try	✓
	Dispensing Nozzle	✓
	Boiler Tank and Water Tank	✗
	Silicon Tubes	✓
	Dispensing valves	✓
	Canisters	✓
	M/C Body (inner and outer)	✓
	Stream Exhaust hose pipe	✓
	Working of Exhaust Fan	✓
	Availability of Canister Elbow	✓
	Application of cockroach Gel	✓

Signature

[BACK TO LIST \(VENDINGCARE/WORKORDER/INDEX?LENGTH=3\)](#)

copyright 2015