



Vending Care....

Work Order Details

Job Details

Asset No 00123 **Job Creation Date** 5/2/2017 12:29:54 PM

Job Start Location **Job End Location** No Location Found

Job Start Date **Job Finish Date** 5/2/2017 12:48:03 PM

Customer Contact No 9582941144 **Customer Email**

Present Status Completed

Remarks 4 lane AC 123

Ingredient Details

Ingredient	Water	Premix	Temperature	Counter
Cardamom Tea	95.00	12.80	83.00	2.00
Coffee	93.00	12.40	84.00	1.00
Soup	90.00	6.20	80.00	4.00
Plain Tea	91.00	12.90	82.00	3.00

Job Images



(http://vendingcare.in/vendingcare/Images/JobImages/97921_1.png)



(http://vendingcare.in/vendingcare/Images/JobImages/97921_2.png)



(http://vendingcare.in/vendingcare/Images/JobImages/97921_3.png)

Work Order Checklist

Parameter Type	Parameter	value
SAFETY		
	EffectiveEarthing	✓
	Good Condition of 3 pin 15 Amp Plug socket	✓
BRANDING		
	Brand and keypad stickers in good condition	✓
	Overall body condition	✓
	No of gell spots found	✗
HYGIENE		

Parameter Type	Parameter	value
	Cleaning and operational instruction sticker	✓
PART CLEANED		
	Mixing Unit	✓
	Drip Try	✓
	Dispensing Nozzle	✓
	Boiler Tank and Water Tank	✓
	Silicon Tubes	✓
	Dispensing valves	✓
	Canisters	✓
	M/C Body (inner and outer)	✓
	Stream Exhaust hose pipe	✓
	Working of Exhaust Fan	✓
	Availability of Canister Elblow	✗
	Application of cockroach Gel	✗

Signature[BACK TO LIST \(/VENDINGCARE/WORKORDER/INDEX?LENGTH=3\)](#)

copyright 2015