



# Vending Care....

## Work Order Details

### Job Details

**Asset No** 28451    **Job Creation Date** 3/15/2017 3:33:14 PM  
**Job Start Location**    **Job End Location**  
**Job Start Date**    **Job Finish Date** 3/15/2017 4:39:38 PM  
**Customer Contact No** 9910921091    **Customer Email** jollyamarsingh@yahoo.com  
**Present Status** Completed

**Remarks** ok

### Ingredient Details

Ingredient	Water	Premix	Temperature	Counter
Cardamom Tea	92.00	10.06	78.50	5.00
Tea Bag with DW	90.00	8.16	76.40	3.00

### Job Images



([http://vendingcare.in/vendingcare/Images/JobImages/88676\\_1.png](http://vendingcare.in/vendingcare/Images/JobImages/88676_1.png))



([http://vendingcare.in/vendingcare/Images/JobImages/88676\\_2.png](http://vendingcare.in/vendingcare/Images/JobImages/88676_2.png))



([http://vendingcare.in/vendingcare/Images/JobImages/88676\\_3.png](http://vendingcare.in/vendingcare/Images/JobImages/88676_3.png))

### Work Order Checklist

Parameter Type	Parameter	value
<b>SAFETY</b>		
	Effective Earthing	✓
	Good Condition of 3 pin 15 Amp Plug socket	✓
<b>BRANDING</b>		
	Brand and keypad stickers in good condition	✓
	Overall body condition	✓
	No of gell spots found	✓
<b>HYGIENE</b>		
	Cleaning and operational instruction sticker	✓
<b>PART CLEANED</b>		

Parameter Type	Parameter	value
	Mixing Unit	✓
	Drip Try	✓
	Dispensing Nozzle	✓
	Boiler Tank and Water Tank	✓
	Silicon Tubes	✓
	Dispensing valves	✓
	Canisters	✓
	M/C Body (inner and outer)	✓
	Stream Exhaust hose pipe	✓
	Working of Exhaust Fan	✓
	Availability of Canister Elbow	✓
	Application of cockroach Gel	✗

**Signature**[BACK TO LIST \(/VENDINGCARE/WORKORDER/INDEX?LENGTH=3\)](#)

copyright 2015