



## Vending Care....

## Work Order Details

## Job Details

**Asset No** 00642 **Job Creation Date** 2/21/2017 4:42:12 PM

**Job Start Location** **Job End Location**

**Job Start Date** **Job Finish Date** 2/21/2017 5:52:40 PM

**Customer Contact No** 9718099191 **Customer Email** fhsbstores@invisiblekitchens.com

**Present Status** Completed

**Remarks** ok

## Ingredient Details

Ingredient	Water	Premix	Temperature	Counter
Cardamom Tea	80.00	7.17	75.60	46817.00
Coffee	80.00	7.23	78.30	11634.00

## Job Images



([http://vendingcare.in/vendingcare/Images/JobImages/84917\\_1.png](http://vendingcare.in/vendingcare/Images/JobImages/84917_1.png))



([http://vendingcare.in/vendingcare/Images/JobImages/84917\\_2.png](http://vendingcare.in/vendingcare/Images/JobImages/84917_2.png))



([http://vendingcare.in/vendingcare/Images/JobImages/84917\\_3.png](http://vendingcare.in/vendingcare/Images/JobImages/84917_3.png))



([http://vendingcare.in/vendingcare/Images/JobImages/84917\\_4.png](http://vendingcare.in/vendingcare/Images/JobImages/84917_4.png))



([http://vendingcare.in/vendingcare/Images/JobImages/84917\\_5.png](http://vendingcare.in/vendingcare/Images/JobImages/84917_5.png))

## Work Order Checklist

Parameter Type	Parameter	value
SAFETY		
	EffectiveEarthing	✓
	Good Condition of 3 pin 15 Amp Plug socket	✓
BRANDING		
	Brand and keypad stickers in good condition	✓
	Overall body condition	✓

Parameter Type	Parameter	value
	No of gell spots found	✓
<b>HYGIENE</b>		
	Cleaning and operational instruction sticker	✓
<b>PART CLEANED</b>		
	Mixing Unit	✓
	Drip Try	✓
	Dispensing Nozzle	✓
	Boiler Tank and Water Tank	✓
	Silicon Tubes	✓
	Dispensing valves	✓
	Canisters	✓
	M/C Body (inner and outer)	✓
	Stream Exhaust hose pipe	✓
	Working of Exhaust Fan	✓
	Availability of Canister Elbow	✗
	Application of cockroach Gel	✗

**Signature**[BACK TO LIST \(VENDINGCARE/WORKORDER/INDEX?LENGTH=3\)](#)

copyright 2015