# Vending Care....



### **Work Order Details**

### Job Details

**Asset No** 26646 **Job Creation Date** 5/4/2017 1:49:02 PM

Job Start Location No Location Found Job End Location No Location Found

Job Start Date 5/4/2017 1:50:55 PM Job Finish Date 5/4/2017 1:58:41 PM

Customer Contact No 9927331533 Customer Email

Present Status Completed

Remarks 27 milk polibag

#### **Ingredient Details**

Ingredient	Water	Premix	Temperature	Counter
Light Tea	0.00	30.00	82.10	2.00
Strong Tea	0.00	35.00	82.10	3.00
Latte with Fresh milk	0.00	12.00	81.70	3.00
Cappucinno with Fresh milk	0.00	18.00	81.10	2.00

## Job Images



(http://vendingcare.in/vendingcare/Images/JobImages/98469\_1.png)



(http://vendingcare.in/vendingcare/Images/JobImages/98469\_2.png)



(http://vendingcare.in/vendingcare/Images/JobImages/98469\_3.png)

#### **Work Order Checklist**

Parameter Type	Patameter	value
SAFETY		
	EffectiveEarthing	×
	Good Condition of 3 pin 15 Amp Plug socket	<b>(2)</b>
BRANDING		
	Brand and keypad stickers in good condition	Ø
	Overall body condition	<b>(2)</b>
	No of gell spots found	×
HYGIENE		

Parameter Type	Patameter	value
	Cleaning and operational instruction sticker	
PART CLEANED		
	Mixing Unit	8
	Drip Try	<b>&amp;</b>
	Dispensing Nozzle	<b>&amp;</b>
	Boiler Tank and Water Tank	<b>&amp;</b>
	Silicon Tubes	8
	Dispensing valves	<b>&amp;</b>
	Canisters	<b>&amp;</b>
	M/C Body (inner and outer)	<b>&amp;</b>
	Stream Exhaust hose pipe	8
	Working of Exhaust Fan	<b>&amp;</b>
	Availability of Canister Elblow	8
	Application of cockroach Gel	8

## Signature



BACK TO LIST (/VENDINGCARE/WORKORDER/INDEX?LENGTH=3)

copyright 2015