

Vending Care....



kapil ▾

Work Order Details

Job Details

Asset No 26695 **Job Creation Date** 4/29/2017 4:26:19 PM

Job Start Location No Location Found **Job End Location** No Location Found

Job Start Date 4/29/2017 4:59:21 PM **Job Finish Date** 4/29/2017 5:27:06 PM

Customer Contact No 9814817010 **Customer Email**


Present Status Completed

Remarks 26695 bc b2c n milk bc 26683

Ingredient Details

Ingredient	Water	Premix	Temperature	Counter
Tea bag with Fresh milk	45.00	45.00	79.00	2.00
Americano	72.00	6.10	80.00	11.00
Latte with Fresh milk	40.00	6.10	79.00	4.00
Cappucinno with Fresh milk	40.00	6.10	79.00	1.00

Job Images



(http://vendingcare.in/vendingcare/Images/JobImages/97602_1.png)



(http://vendingcare.in/vendingcare/Images/JobImages/97602_2.png)



(http://vendingcare.in/vendingcare/Images/JobImages/97602_3.png)



(http://vendingcare.in/vendingcare/Images/JobImages/97602_4.png)

Work Order Checklist

Parameter Type	Parameter	value
SAFETY		
	Effective Earthing	✓
	Good Condition of 3 pin 15 Amp Plug socket	✓
BRANDING		
	Brand and keypad stickers in good condition	✓

Parameter Type	Parameter	value
	Overall body condition	✘
	No of gell spots found	✘
HYGIENE		
	Cleaning and operational instruction sticker	✔
PART CLEANED		
	Mixing Unit	✘
	Drip Try	✘
	Dispensing Nozzle	✘
	Boiler Tank and Water Tank	✘
	Silicon Tubes	✘
	Dispensing valves	✘
	Canisters	✘
	M/C Body (inner and outer)	✘
	Stream Exhaust hose pipe	✘
	Working of Exhaust Fan	✘
	Availability of Canister Elbow	✘
	Application of cockroach Gel	✘

Signature[BACK TO LIST \(/VENDINGCARE/WORKORDER/INDEX?LENGTH=3\)](#)

copyright 2015