



# Vending Care....

## Work Order Details

### Job Details

**Asset No** 32791 **Job Creation Date** 4/18/2017 12:35:24 PM

**Job Start Location** **Job End Location** No Location Found

**Job Start Date** **Job Finish Date** 4/18/2017 3:30:17 PM

**Customer Contact No** 120 **Customer Email** no

**Present Status** Completed

**Remarks** ok

### Ingredient Details

Ingredient	Water	Premix	Temperature	Counter
Cardamom Tea	92.00	12.54	83.60	7.00
Coffee	93.00	12.54	84.40	8.00
Tea Bag with DW	92.00	11.44	82.90	7.00
Hot Lemon Tea	93.00	11.74	81.50	8.00

### Job Images



([http://vendingcare.in/vendingcare/Images/JobImages/95083\\_1.png](http://vendingcare.in/vendingcare/Images/JobImages/95083_1.png))



([http://vendingcare.in/vendingcare/Images/JobImages/95083\\_2.png](http://vendingcare.in/vendingcare/Images/JobImages/95083_2.png))



([http://vendingcare.in/vendingcare/Images/JobImages/95083\\_3.png](http://vendingcare.in/vendingcare/Images/JobImages/95083_3.png))

### Work Order Checklist

Parameter Type	Parameter	value
<b>SAFETY</b>		
	EffectiveEarthing	✓
	Good Condition of 3 pin 15 Amp Plug socket	✓
<b>BRANDING</b>		
	Brand and keypad stickers in good condition	✓
	Overall body condition	✗
	No of gell spots found	✗
<b>HYGIENE</b>		

Parameter Type	Parameter	value
	Cleaning and operational instruction sticker	✓
<b>PART CLEANED</b>		
	Mixing Unit	✓
	Drip Try	✓
	Dispensing Nozzle	✓
	Boiler Tank and Water Tank	✓
	Silicon Tubes	✓
	Dispensing valves	✓
	Canisters	✗
	M/C Body (inner and outer)	✓
	Stream Exhaust hose pipe	✓
	Working of Exhaust Fan	✓
	Availability of Canister Elbow	✓
	Application of cockroach Gel	✗

**Signature**[BACK TO LIST \(/VENDINGCARE/WORKORDER/INDEX?LENGTH=3\)](#)

copyright 2015