



Vending Care....

Work Order Details

Job Details

Asset No 01929 **Job Creation Date** 3/29/2017 2:42:32 PM

Job Start Location **Job End Location** No Location Found

Job Start Date **Job Finish Date** 3/29/2017 2:57:27 PM

Customer Contact No 9891248395 **Customer Email** mahesh.bisht@jaypore.com

Present Status Completed

Remarks

Ingredient Details

Ingredient	Water	Premix	Temperature	Counter
Tea bag with Fresh milk	70.00	55.00	79.00	606.00
Latte with Fresh milk	40.00	6.90	78.00	24.00
Cappucinno with Fresh milk	40.00	7.50	79.00	1806.00
Americano	73.00	6.70	77.00	188.00

Job Images



(http://vendingcare.in/vendingcare/Images/JobImages/90986_1.png)



(http://vendingcare.in/vendingcare/Images/JobImages/90986_2.png)



(http://vendingcare.in/vendingcare/Images/JobImages/90986_3.png)



(http://vendingcare.in/vendingcare/Images/JobImages/90986_4.png)



(http://vendingcare.in/vendingcare/Images/JobImages/90986_5.png)



(http://vendingcare.in/vendingcare/Images/JobImages/90986_6.png)

Work Order Checklist

Parameter Type	Parameter	value
SAFETY		

Parameter Type	Parameter	value
	Effective Earthing	✓
	Good Condition of 3 pin 15 Amp Plug socket	✓
BRANDING		
	Brand and keypad stickers in good condition	✓
	Overall body condition	✓
	No of gell spots found	✓
HYGIENE		
	Cleaning and operational instruction sticker	✓
PART CLEANED		
	Mixing Unit	✓
	Drip Tray	✓
	Dispensing Nozzle	✓
	Boiler Tank and Water Tank	✓
	Silicon Tubes	✓
	Dispensing valves	✓
	Canisters	✓
	M/C Body (inner and outer)	✓
	Stream Exhaust hose pipe	✓
	Working of Exhaust Fan	✓
	Availability of Canister Elbow	✓
	Application of cockroach Gel	✓

Signature


[BACK TO LIST \(/VENDINGCARE/WORKORDER/INDEX?LENGTH=3\)](#)

copyright 2015