Vending Care....



Work Order Details

Job Details

Asset No 28359 Job Creation Date 2/28/2017 3:19:48 PM

Job Start Location Job End Location

Job Start Date 2/28/2017 4:08:05 PM Job Finish Date 2/28/2017 4:43:45 PM

Customer Contact No 01143288888 Customer Email krish.del.sal2@marutidealers.com

Present Status Completed

Remarks tea leaf not alebal, es liye tea ki seting nahi ho pai hai

Ingredient Details

Ingredient	Water	Premix	Temperature	Counter
Tea bag with Fresh milk	0.00	0.00	82.00	4.00
Latte with Fresh milk	13.00	0.00	82.00	4.00
Cappucinno with Fresh milk	18.00	0.00	82.00	14.00
Americano	18.00	0.00	82.00	9.00

Job Images



(http://vendingcare.in/vendingcare/Images/JobImages/86322_1.png)



(http://vendingcare.in/vendingcare/Images/JobImages/86322_2.png)



(http://vendingcare.in/vendingcare/Images/JobImages/86322_3.png)



(http://vendingcare.in/vendingcare/Images/JobImages/86322_4.png)



(http://vendingcare.in/vendingcare/Images/JobImages/86322_5.png)



(http://vendingcare.in/vendingcare/Images/JobImages/86322_6.png)



(http://vendingcare.in/vendingcare/Images/JobImages/86322_7.png)

Work Order Checklist

Parameter Type	Patameter	value
SAFETY		
	EffectiveEarthing	✓
	Good Condition of 3 pin 15 Amp Plug socket	√
BRANDING		
	Brand and keypad stickers in good condition	√
	Overall body condition	8
	No of gell spots found	8
HYGIENE		
	Cleaning and operational instruction sticker	√
PART CLEANED		
	Mixing Unit	8
	Drip Try	8
	Dispensing Nozzle	8
	Boiler Tank and Water Tank	S
	Silicon Tubes	S
	Dispensing valves	8
	Canisters	8
	M/C Body (inner and outer)	√
	Stream Exhaust hose pipe	1
	Working of Exhaust Fan	√
	Availability of Canister Elblow	S
	Application of cockroach Gel	8

Signature

BACK TO LIST (/VENDINGCARE/WORKORDER/INDEX?LENGTH=3)

copyright 2015