

## Vending Care....



kapil ▾

## Work Order Details

## Job Details

**Asset No** 30902 **Job Creation Date** 2/7/2017 11:26:07 AM

**Job Start Location** No Location Found **Job End Location** No Location Found

**Job Start Date** 2/9/2017 4:59:22 PM **Job Finish Date** 2/9/2017 5:04:51 PM

**Customer Contact No** 9814873284 **Customer Email**

**Present Status** Completed

**Remarks** Done on 11/1/2017


## Ingredient Details

Ingredient	Water	Premix	Temperature	Counter
Tea bag with Fresh milk	120.00	30.00	77.00	8.00
Latte with Fresh milk	155.00	15.00	78.00	4.00
Cappucinno with Fresh milk	150.00	20.00	78.00	11.00

## Job Images



([http://vendingcare.in/vendingcare/Images/JobImages/82051\\_1.png](http://vendingcare.in/vendingcare/Images/JobImages/82051_1.png))



([http://vendingcare.in/vendingcare/Images/JobImages/82051\\_2.png](http://vendingcare.in/vendingcare/Images/JobImages/82051_2.png))



([http://vendingcare.in/vendingcare/Images/JobImages/82051\\_3.png](http://vendingcare.in/vendingcare/Images/JobImages/82051_3.png))



([http://vendingcare.in/vendingcare/Images/JobImages/82051\\_4.png](http://vendingcare.in/vendingcare/Images/JobImages/82051_4.png))

## Work Order Checklist

Parameter Type	Parameter	value
SAFETY		
	Effective Earthing	✓
	Good Condition of 3 pin 15 Amp Plug socket	✓
BRANDING		
	Brand and keypad stickers in good condition	✓
	Overall body condition	✓

Parameter Type	Parameter	value
	No of gell spots found	✓
<b>HYGIENE</b>		
	Cleaning and operational instruction sticker	✓
<b>PART CLEANED</b>		
	Mixing Unit	✓
	Drip Try	✓
	Dispensing Nozzle	✓
	Boiler Tank and Water Tank	✓
	Silicon Tubes	✓
	Dispensing valves	✓
	Canisters	✓
	M/C Body (inner and outer)	✓
	Stream Exhaust hose pipe	✓
	Working of Exhaust Fan	✓
	Availability of Canister Elblow	✓
	Application of cockroach Gel	✗

**Signature**



[BACK TO LIST \(VENDINGCARE/WORKORDER/INDEX?LENGTH=3\)](#)

copyright 2015