



Vending Care....

Work Order Details

Job Details

Asset No 00102 **Job Creation Date** 12/21/2016 11:03:36 AM

Job Start Location No Location Found **Job End Location** No Location Found

Job Start Date 12/21/2016 11:06:11 AM **Job Finish Date** 12/21/2016 12:00:15 PM

Customer Contact No 9650182188 **Customer Email** sudhirsst56@yahoo.co.in

Present Status Completed

Remarks

Ingredient Details

| Ingredient | Water | Premix | Temperature | Counter |
|--------------|--------|--------|-------------|-----------|
| Cardamom Tea | 133.00 | 13.46 | 83.90 | 170985.00 |
| Coffee | 132.00 | 14.32 | 82.70 | 143261.00 |

Job Images



(http://vendingcare.in/vendingcare/Images/JobImages/73212_1.png)



(http://vendingcare.in/vendingcare/Images/JobImages/73212_2.png)



(http://vendingcare.in/vendingcare/Images/JobImages/73212_3.png)

Work Order Checklist

| Parameter Type | Parameter | value |
|---------------------|--|-------|
| SAFETY | | |
| | Effective Earthing | ✘ |
| | Good Condition of 3 pin 15 Amp Plug socket | ✔ |
| BRANDING | | |
| | Brand and keypad stickers in good condition | ✔ |
| | Overall body condition | ✔ |
| | No of gell spots found | ✘ |
| HYGIENE | | |
| | Cleaning and operational instruction sticker | ✔ |
| PART CLEANED | | |

| Parameter Type | Parameter | value |
|----------------|--------------------------------|-------|
| | Mixing Unit | ✓ |
| | Drip Try | ✓ |
| | Dispensing Nozzle | ✓ |
| | Boiler Tank and Water Tank | ✓ |
| | Silicon Tubes | ✓ |
| | Dispensing valves | ✓ |
| | Canisters | ✓ |
| | M/C Body (inner and outer) | ✓ |
| | Stream Exhaust hose pipe | ✓ |
| | Working of Exhaust Fan | ✓ |
| | Availability of Canister Elbow | ✓ |
| | Application of cockroach Gel | ✗ |

Signature[BACK TO LIST \(/VENDINGCARE/WORKORDER/INDEX?LENGTH=3\)](#)

copyright 2015