



Vending Care....

Work Order Details

Job Details

Asset No 28348 **Job Creation Date** 3/24/2017 7:39:29 PM

Job Start Location No Location Found **Job End Location** No Location Found

Job Start Date 3/24/2017 10:01:16 PM **Job Finish Date** 3/25/2017 2:51:28 AM

Customer Contact No 8586058951 **Customer Email** devendra12580@gmail.com


Present Status Completed

Remarks traing ♦♦ devendra 30 polibag

Ingredient Details

Ingredient	Water	Premix	Temperature	Counter
Light Tea	0.00	30.00	80.50	3.00
Strong Tea	0.00	35.00	80.70	2.00
Latte with Fresh milk	0.00	12.00	80.80	3.00
Cappucinno with Fresh milk	0.00	18.00	80.90	2.00

Job Images



(http://vendingcare.in/vendingcare/Images/JobImages/90288_1.png)



(http://vendingcare.in/vendingcare/Images/JobImages/90288_2.png)




(http://vendingcare.in/vendingcare/Images/JobImages/90288_3.png)



(http://vendingcare.in/vendingcare/Images/JobImages/90288_4.png)




(http://vendingcare.in/vendingcare/Images/JobImages/90288_5.png)



(http://vendingcare.in/vendingcare/Images/JobImages/90288_6.png)



(http://vendingcare.in/vendingcare/Images/JobImages/90288_7.png)



(http://vendingcare.in/vendingcare/Images/JobImages/90288_8.png)



(http://vendingcare.in/vendingcare/Images/JobImages/90288_9.png)

Work Order Checklist

Parameter Type	Parameter	value
SAFETY		
	Effective Earthing	✓
	Good Condition of 3 pin 15 Amp Plug socket	✓
BRANDING		
	Brand and keypad stickers in good condition	✓
	Overall body condition	✓
	No of gell spots found	✗
HYGIENE		
	Cleaning and operational instruction sticker	✗
PART CLEANED		
	Mixing Unit	✗
	Drip Tray	✓
	Dispensing Nozzle	✓
	Boiler Tank and Water Tank	✗
	Silicon Tubes	✓
	Dispensing valves	✓
	Canisters	✓
	M/C Body (inner and outer)	✓
	Stream Exhaust hose pipe	✓
	Working of Exhaust Fan	✓
	Availability of Canister Elbow	✗
	Application of cockroach Gel	✗

Signature

Dc ✓

[BACK TO LIST \(VENDINGCARE/WORKORDER/INDEX?LENGTH=3\)](#)

copyright 2015

