



# Vending Care....

## Work Order Details

### Job Details

**Asset No** 30969 **Job Creation Date** 4/1/2017 4:48:42 PM

**Job Start Location** No Location Found **Job End Location** No Location Found

**Job Start Date** 4/1/2017 4:50:23 PM **Job Finish Date** 4/1/2017 7:34:22 PM

**Customer Contact No** 9041419721 **Customer Email**

**Present Status** Completed

**Remarks** 30969 bc bru gold installation done

### Ingredient Details

Ingredient	Water	Premix	Temperature	Counter
Tea bag with Fresh milk	45.00	45.00	83.00	722.00
Latte with Fresh milk	30.00	1.40	82.00	358.00
Cappucinno with Fresh milk	30.00	1.40	82.00	391.00
Cardamom Tea	130.00	14.50	81.00	37.00

### Job Images



([http://vendingcare.in/vendingcare/Images/JobImages/91865\\_1.png](http://vendingcare.in/vendingcare/Images/JobImages/91865_1.png))



([http://vendingcare.in/vendingcare/Images/JobImages/91865\\_2.png](http://vendingcare.in/vendingcare/Images/JobImages/91865_2.png))



([http://vendingcare.in/vendingcare/Images/JobImages/91865\\_3.png](http://vendingcare.in/vendingcare/Images/JobImages/91865_3.png))



([http://vendingcare.in/vendingcare/Images/JobImages/91865\\_4.png](http://vendingcare.in/vendingcare/Images/JobImages/91865_4.png))

### Work Order Checklist

Parameter Type	Parameter	value
<b>SAFETY</b>		
	Effective Earthing	✓
	Good Condition of 3 pin 15 Amp Plug socket	✓
<b>BRANDING</b>		
	Brand and keypad stickers in good condition	✓

Parameter Type	Parameter	value
	Overall body condition	✘
	No of gell spots found	✘
<b>HYGIENE</b>		
	Cleaning and operational instruction sticker	✔
<b>PART CLEANED</b>		
	Mixing Unit	✘
	Drip Try	✘
	Dispensing Nozzle	✘
	Boiler Tank and Water Tank	✘
	Silicon Tubes	✘
	Dispensing valves	✘
	Canisters	✘
	M/C Body (inner and outer)	✘
	Stream Exhaust hose pipe	✘
	Working of Exhaust Fan	✘
	Availability of Canister Elbow	✘
	Application of cockroach Gel	✘

**Signature**

BTHU

[BACK TO LIST \(/VENDINGCARE/WORKORDER/INDEX?LENGTH=3\)](#)

copyright 2015